

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20001902/KGA3Q2
Date: 10/05/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKM1892L	Insured Vehicle No :	SHA3533J
Date of Loss:	13/01/2020	Nature of Claim:	TP
		Claim No:	MCT20010304

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM1892L		
Make & Model:	MERCEDES-BENZ E200, 2.0 (A)	Engine No:	27492030104007
Reg. Date:	28/01/2014 (Man. Year: 2013)	Chassis No:	WDD2074342F242128
Colour:	Metallic Pearl White	Odometer:	64837 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	255/35Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,792.50	4,146.59	12,645.91	75.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,060.00	1,750.00	62.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,602.50	5,206.59	14,395.91	73.44
Approved Total (Overridden) (S\$)		4,150.00		

Nett Amount (S\$)	19,602.50	4,150.00	15,452.50	78.83
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,056.25		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 04/02/2020

Estimated Period of Repair: 5.0 days

Inspected At: Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM1892L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Dented / Cracked	1,452.50 F	*1,321.20 FL
2	1		*FRONT FENDER DUST COVER	Serviceable	341.90 F	*- FL
3	1		*FRONT BUMPER	Buckled	2,652.70 F	*1,514.63 FL
4	1		*FRONT BUMPER SIDE BRACKET	Distorted	122.60 F	*122.60 FL
5	1		*FRONT HEAD LAMP (CUT)	Not Consistent With The Impact	3,267.30 F	*- FL
6	1		*FRONT BUMPER PARK ASSIST SENSOR	Scratched	846.00 F	*260.00 FL
7	1		*FRONT BUMPER LOWER CHROME MOULDING	Serviceable	664.30 F	*- FL
8	1		*FRONT BUMPER SIDE GRILLE	Serviceable	565.00 F	*- FL
9	1		*FRONT SHOCK ABSORBER	Serviceable	993.30 F	*- FL
10	1		*FRONT KNUCKLE ARM	Serviceable	865.40 F	*- FL
11	1		*FRONT WHEEL HUB BEARING	Serviceable	464.70 F	*- FL
12	1		*FRONT LOWER ARM	Serviceable	844.80 F	*- FL
13	1		*FRONT STEERING TIE ROD	Serviceable	374.30 F	*- FL
14	1		*FRONT TRUST CONTROL ARM	Serviceable	586.40 F	*- FL
15	1		*FRONT ANTIROLL BAR LINKAGE	Serviceable	321.30 F	*- FL
16	1		*FRONT LOWER ARM BALL JOINT	Serviceable	275.40 F	*- FL
17	1		*AMG 18 ALLOY ARM	Dented	1,780.00 FS	*1,250.00 FS
18	1		*FRONT BUMPER AIR PRESSURE SENSOR	Not Applicable	374.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,792.50	4,468.43
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	321.84
Total Parts (S\$)	16,792.50	4,146.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY TOOLS AND LABOUR FOR REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,REALIGN PANEL FOR FITMENT	New	900.00	400.00
2	TO SUPPLY MATERIALS ,PUTTY & SPRAY PAINT ON AFFECTED AREAS	New	800.00	500.00
3	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE TO REPAIR	New	450.00	0.00
4	TO CHECK WIRING SYSTEM ,DIAGNOSIS WITH XENTRY	New	250.00	0.00
5	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
6	TO REPLACE ALLOY RIM & PERFORM WHEEL BALANCING	New	45.00	20.00
7	TO INSTALL PARKING SENSORS AND CARIBRATE WITH XENTRY	New	280.00	80.00
Gross Labour Cost (S\$)			2,810.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >