

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001905/AES3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485975
Claimant
Vehicle No : SLQ4543S **Insured Vehicle No :** SLG6759B
Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: 2106368742SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ4543S**
Make & Model: MERCEDES-BENZ CLA180, 1.6 (A) Engine No: 27091031269694
Reg. Date: 11/07/2017 (Man. Year: 2017) Chassis No: WDD1173422N504233
Colour: White Odometer: 47010 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,515.00	4,642.20	3,872.80	45.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,130.00	2,820.00	71.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,465.00	5,772.20	6,692.80	53.69
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	12,465.00	4,600.00	7,865.00	63.10
+ GST 7.00/7.00% (S\$)	872.55	322.00	550.55	63.10
Nett Amount (S\$)	13,337.55	4,922.00	8,415.55	63.10
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,169.45		

INSPECTION

Date of Assignment: 03/02/2020
Date Inspected: 04/02/2020 Inspected At: Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER INNER COWLING LH	Torn	250.00 FL	*250.00 FL
2	1		*REAR FENDER AIR VENT LH	Cracked	105.00 FL	*105.00 FL
3	1		*REAR FENDER AIR VENT PANEL LH	Repair	560.00 FL	*- FL
4	1		*TAIL LAMP LH	Cracked	900.00 FL	*900.00 FL
5	1		*TAIL LAMP LOWER BRACKET LH	Deformed	129.00 FL	*129.00 FL
6	1		*REAR BUMPER	Deformed	1,585.00 FL	*1,585.00 FL
7	1		*REAR BUMPER DIFFUSER	Cracked	490.00 FL	*490.00 FL
8	1		*REAR BUMPER REVERSE SENSOR LH	Damaged	265.00 FL	*265.00 FL
9	1		*REAR BUMPER SENSOR HOLDER (6 PCS)	Necessary (1 PCS ONLY)	384.00 FL	*64.00 FL
10	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	150.00 FL	*75.00 FL
11	1		*REAR BUMPER CENTER BEAM	Not Necessary	162.00 FL	*- FL
12	1		*REAR BUMPER SIDE LOWER BRACKET LH	Not Necessary	60.00 FL	*- FL
13	1		*REAR BUMPER CORNER LOWER BRACKET LH	Cracked	68.00 FL	*68.00 FL
14	1		*REAR BUMPER SIDE AIR VENT GARNISH	Not Necessary	162.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	850.00 FL	*850.00 FL
16	1		*REAR BUMPER EXHAUST CHROME PIPE LH	Not Necessary	440.00 FL	*- FL
17	1		*REAR BUMPER EXHAUST CHROME PIPE BRACKET LH	Not Necessary	165.00 FL	*- FL
18	1		*REAR EXHAUST INSULATOR	Cracked	735.00 FL	*277.00 FL
19	1		*REAR END PANEL	Repair	1,290.00 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	120.00 FS	*50.00 FS
21	1		*SET REAR BUMPER SIDE AIR VENT GARNISH CLIP	Not Necessary	50.00 FS	*- FS
22	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
23	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
24	1		*SET REAR FENDER INNER COWLING CLIP LH	Necessary	80.00 FS	*30.00 FS
25	1		*REAR FENDER AIR VENT PANEL SEALANT LH	Not Necessary	80.00 FS	*- FS
26	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
27	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,390.00	5,148.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	875.00	505.80
Total Parts (\$\$)	8,515.00	4,642.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	250.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
7	REMOVE & REINSTALL & RESET REVERSE SENSOR	New	200.00	60.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET/MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (S\$)			3,950.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >