

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail:visionautowork@gmail.com

DATE : 03.02.20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ4543S**
 MODEL : **MERCEDES CLA180**
 DATE OF ACCIDENT : 01.02.20
 TIME OF ACCIDENT : 11:00HRS

WDD1173422X504233
 Asher.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER INNER COWLING LH <i>torn</i>	1	\$ 250.00	\$ 250.00
2	REAR FENDER AIR VENT LH <i>cracked</i>	1	\$ 105.00	\$ 105.00
3	REAR FENDER AIR VENT PANEL LH <i>Repair</i>	1	\$ 560.00	\$ 560.00
4	TAIL LAMP LH <i>cracked</i>	1	\$ 900.00	\$ 900.00
5	TAIL LAMP LOWER BRACKET LH <i>del</i>	1	\$ 129.00	\$ 129.00
6	REAR BUMPER <i>del</i>	1	\$ 1,585.00	\$ 1,585.00
7	REAR BUMPER DIFFUSER <i>cracked</i>	1	\$ 490.00	\$ 490.00
8	REAR BUMPER REVERSE SENSOR LH <i>Paint</i>	1	\$ 265.00	\$ 265.00
9	REAR BUMPER SENSOR HOLDER <i>New</i>	6 <i>(pieces)</i>	\$ 64.00	\$ 384.00
10	REAR BUMPER SIDE RETAINER <i>cracked hit</i>	2	\$ 75.00	\$ 150.00
11	REAR BUMPER CENTER BEAM <i>New</i>	1	\$ 162.00	\$ 162.00
12	REAR BUMPER SIDE LOWER BRACKET LH <i>New</i>	1	\$ 60.00	\$ 60.00
13	REAR BUMPER CORNER LOWER BRACKET LH <i>cracked</i>	1	\$ 68.00	\$ 68.00
14	REAR BUMPER SIDE AIR VENT GARNISH <i>New</i>	1	\$ 162.00	\$ 162.00
15	REAR BUMPER REINFORCEMENT <i>New Best</i>	1	\$ 850.00	\$ 850.00
16	REAR BUMPER EXHAUST CHROME PIPE LH <i>New</i>	1	\$ 440.00	\$ 440.00
17	REAR BUMPER EXHAUST CHROME PIPE BRACKET LH <i>New</i>	1	\$ 165.00	\$ 165.00
18	REAR EXHAUST INSULATOR <i>New Cracked</i>	1	\$ 735.00	\$ 735.00
19	REAR END PANEL <i>Repair</i>	1	\$ 1,290.00	\$ 1,290.00

5058
 4552.20
 TOTAL PRICE \$ 8,750.00
 LESS 10% \$ 875.00
 SUB TOTAL PRICE \$ 7,875.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 120.00	\$ 120.00
2	REAR BUMPER SIDE AIR VENT GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
3	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
4	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ4543S**
 MODEL : **MERCEDES CLA180**
 DATE OF ACCIDENT : 01.02.20
 TIME OF ACCIDENT : 11:00HRS

5	REAR FENDER INNER COWLING CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	REAR FENDER AIR VENT PANEL SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
7	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
8	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
<i>90</i>			TOTAL	\$ 640.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>400</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>40</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
6	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>x</i>
7	REMOVE & REINSTALL & RESET REVERSE SENSOR	\$ 200.00	<i>60</i>
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	<i>x</i>
TOTAL		\$ 3,950.00	<i>1130</i>

TOTAL PARTS COST : \$ 8,515.00
 TOTAL LABOUR COST : \$ 3,950.00
 TOTAL REPAIR COST : \$ 12,465.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- no illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin Lj
l/s 04/02/20
04 days
total: 5772.20
l/s: 4.61c