

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001913/KPS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100411236

Claimant
Vehicle No : SKU2175A **Insured Vehicle No :** GBD7826T

Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: 4466676294SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2175A	Engine No:	K24W71000899
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMR1890EC201502
Reg. Date:	07/05/2014 (Man. Year: 2014)	Odometer:	115034 km
Colour:	Metallic Pearl White		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dayton 8 mm	Rear Left Side:	Dayton 8 mm
Front Right Side:	Dayton 8 mm	Rear Right Side:	Dayton 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,430.76	8,713.04	2,717.72	23.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,750.00	3,030.00	2,720.00	47.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,180.76	11,743.04	5,437.72	31.65
Approved Total (Overridden) (S\$)		9,400.00		
(S\$)	17,180.76	9,400.00	7,780.76	45.29
+ GST 7.00/7.00% (S\$)	1,202.65	658.00	544.65	45.29
Nett Amount (S\$)	18,383.41	10,058.00	8,325.41	45.29
+ Car Rental (18.0 x S\$150.00/day + 7.00% GST) (S\$)		2,889.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,954.45		
Global Sum Settlement (S\$)		12,950.00		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 04/02/2020 Inspected At:

385 SIN MING DRIVE

Repairer: Esteem Performance Pte Ltd (HQ)

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
2	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
3	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
4	1		*REAR BUMPER	Bent	657.20 FL	*657.20 FL
5	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	30.00 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Distorted	30.00 FL	*30.00 FL
8	1		*REAR BUMPER BRACKET LH (NPA)	Serviceable	0.00 FL	*- FL
9	1		*REAR BUMPER BRACKET RH (NPA)	Serviceable	0.00 FL	*- FL
10	1		*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT (NPA)	Serviceable	0.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Cracked	65.40 FL	*65.40 FL
13	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
14	1		*TAIL DOOR	Bent	1,293.00 FL	*1,293.00 FL
15	1		*TAIL DOOR LOCK	Repair	239.00 FL	*- FL
16	1		*TAIL DOOR TRIM }	Repair	292.30 FL	*- FL
17	10		*TAIL DOOR TRIM CLIP }		0.00 FL	*- FL
18	1		*TAIL DOOR REFLECTOR LH	Broken	428.60 FL	*428.60 FL
19	1		*TAIL DOOR REFLECTOR RH	Cracked	428.60 FL	*428.60 FL
20	1		*TAIL DOOR REFLECTOR CENTRE	Serviceable	330.30 FL	*- FL
21	1		*TAIL DOOR CENTRE CHROME	Warped	245.00 FL	*245.00 FL
22	1		*TAIL END PANEL	Bent	551.80 FL	*551.80 FL
23	1		*TAIL END PANEL GARNISH	Serviceable	155.00 FL	*- FL
24	10		*TAIL END PANEL GARNISH CLIP (NPA)	Serviceable	0.00 FL	*- FL
25	1		*BOOT WEATHERSTRIP	Serviceable	150.90 FL	*- FL
26	1		*TAIL LAMP LH	Serviceable	871.80 FL	*- FL
27	1		*TAIL LAMP RH	Mtg Cracked	871.80 FL	*871.80 FL
28	1		*SPARE TYRE WELL PANEL	Repair	381.30 FL	*- FL
29	1		*SPARE TYRE BOARD	Serviceable	384.10 FL	*- FL
30	1		*SPARE TYRE COMPARTMENT SPONGE LH (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*SPARE TYRE COMPARTMENT SPONGE RH (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*SPARE TYRE COMPARTMENT CENTRE (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*RH REAR FENDER	Buckled	1,073.70 FL	*1,073.70 FL
34	1		*RH REAR FENDER UNDERSHIELD	Distorted	166.30 FL	*166.30 FL
35	10		*RH REAR FENDER UNDERSHIELD CLIP	Necessary	35.00 FL	*35.00 FL
36	1		*RH REAR FENDER AIR DUST	Serviceable	45.70 FL	*- FL
37	1		*RH REAR INNER TRIM	Mtg Cracked	899.10 FL	*899.10 FL
38	10		*RH REAR INNER TRIM CLIP	Not Necessary	45.00 FL	*- FL
39	1		*AIR BAG ROOF TOP LH	Burst	910.70 FL	*910.70 FL
40	1		*AIR BAG CONTROL UNIT	Necessary	1,034.70 FL	*1,034.70 FL
41	1		*ROOF LINING	Deformed	1,041.80 FL	*1,041.80 FL
42	10		*ROOF LINING CLIP	Necessary	55.00 FL	*55.00 FL
43	1		*EXHAUST PIPE	Bent	686.80 FL	*686.80 FL
44	1		*EXHAUST PIPE MOUNTING	Serviceable	56.50 FL	*- FL
45	1		*EXHAUST INSULATOR	Serviceable	96.50 FL	*- FL
46	1		*RH REAR BUMPER GARNISH	Dented	76.80 FL	*76.80 FL
47	1		*RH RADAR COVER	Dented	60.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,214.70 10,881.30
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,783.94 2,168.26

Total Parts (\$\$) 11,430.76 8,713.04

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAIL DOOR ,END PANEL,SPARE TYRE COMPARTMENT ,RHR FENDER ,RHR DOOR,REAR CHASSIC RH)	New	1,800.00	1,200.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAIL DOOR ,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER ,RHR DOOR REAR CHASSIS RH)	New	1,800.00	1,000.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO DO WHEEL ALIGNMENT	New	120.00	0.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	TO TUFF COAT	New	250.00	90.00
7	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	250.00	120.00
8	TO REMOVE & REFIT ROOF LINING ,INNER TRIM TO ASSIST WORK LOAD	New	400.00	200.00
9	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New	150.00	60.00
10	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
11	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
12	TO RE-ALIGN REAR CHASSIC	New	300.00	0.00
13	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPER TRIM ,TO ASSIST WORK LOAD	New	150.00	80.00
14	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			5,750.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >