



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKU 2175 A

Parts	(a) Cost / List Price Items	\$	13,782.90
	Plus/Less 20%	\$	2,756.58
	Total of Cost / List	\$	11,026.32
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	11,321.32
Labour		\$	5,750.00
Total		\$	17,071.32

*Not Authorized
Repairing After Rain
L/Ring B?*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenner

Company

:

LKK

Survey conducted on

:

4/2/20

at

Remarks By Surveyor

(a) The repair of this vehicle is *authorized* / is not authorized until further notice.

(b) Recommended Days of Repair : *16* day(s)

(c) Resurvey : Required / *Not Required*

(d) Excess : \$

(e) Signature of surveyor

:

Sc

Date:

4/2/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKU 2175 A**
Make & Model : **HONDA ODYSSEY**
Chassis No : **JHMRC1890EC201502**

Submit By : **JENNY**
Year Manufacture : **2014**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>RM</i>	1	\$195.00		✓
2	Rear windscreen sealant <i>RM</i>	1	\$50.00	S.N	4052
3	Reverse sensor	1	\$200.00	S.N	7
4	Rear bumper <i>RM</i>	1	\$657.20		✓
5	Rear bumper clip <i>RM</i>	10	\$35.00		✓
6	Rear bumper side retainer LH	1	\$30.00		
7	Rear bumper side retainer RH <i>RM</i>	1	\$30.00		✓
8	Rear bumper bracket LH	1	N/A		
9	Rear bumper bracket RH	1	N/A		
10	Rear bumper sponge	1	N/A		
11	Rear bumper reinforcement	1	N/A		
12	Rear bumper reflector RH	1	\$65.40		
13	Rear number plate <i>RM</i>	1	\$45.00	S.N	X
14	Tail door <i>RM</i>	1	\$1,293.00		✓
15	Tail door lock	1	\$239.00		7
16	Tail door trim	1	\$292.30		7
17	Tail door trim clip	10			
18	Tail door reflector LH <i>RM</i>	1	\$428.60		✓
19	Tail door reflector RH <i>RM</i>	1	\$428.60		✓
20	Tail door reflector centre	1	\$330.30		7
21	Tail door centre chrome <i>RM</i>	1	\$245.00		✓
22	Tail end panel <i>RM</i>	1	\$551.80		✓
23	Tail end panel garnish	1	\$155.00		7

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SKU 2175 A**

Make & Model : **HONDA ODYSSEY**

Chassis No : **JHMRC1890EC201502**

Submit By : **Carmen Lim**

Year Manufacture : **2014**

Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip	10	N.A		
25	Boot weatherstrip	1	\$150.90		?
26	Tail lamp LH <i>Re</i>	1	\$871.80		X
27	Tail lamp RH	1	\$871.80		?
28	Spare tyre well panel	1	\$381.30		?
29	Spare tyre board	1	\$384.10		?
30	Spare tyre compartment sponge LH	1	TBA		
31	Spare tyre compartment sponge RH	1	TBA		
32	Spare tyre compartment centre	1	TBA		
33	RH rear fender <i>Br</i>	1	\$1,073.70		—
34	RH rear fender undershield <i>Br</i>	1	\$166.30		—
35	RH rear fender undershield clip <i>Re</i>	10	\$35.00		—
36	RH rear fender air duct	1	\$45.70		?
37	RH rear inner trim	1	\$899.10		?
38	RH rear inner trim clip	10	\$45.00		?
39	Air bag roof top LH <i>Br</i>	1	\$910.70		—
40	Air bag control unit <i>Re</i>	1	\$1,034.70		—
41	Roof Lining <i>Re turn</i>	1	\$1,041.80		—
42	Roof lining clip <i>Re</i>	10	\$55.00		—
43	Exhaust pipe <i>Br</i>	1	\$686.80		—
44	Exhaust pipe mouting	1	\$56.50		?
45	Exhaust insulator	1	\$96.50		?
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKU 2175 A** Submit By : **Carmen Lim**
Make & Model : **HONDA ODYSSEY** Year of Manufacture : **2014**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, REAR CHASSIC RH)	\$1,800.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, REAR CHASSIC RH)	\$1,800.00	1000
3	TO Check wiring	\$50.00	20
4	To do wheel alignment.	\$120.00	7
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$250.00	90
7	To remove & refit inner seat & upholstery to assist work load.	\$250.00	120
8	To remove & refit roof lining, inner trim to assist work load.	\$400.00	200
9	To remove & refit exhaust system to assist work load.	\$150.00	60
10	To transfer boot mechanism to new boot	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SKU 2175 A**

Submit By : : **Carmen Lim**

Make & Model : HONDA ODYSSEY

Year of Manufacture : 2014

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.