



jenny chong <jenny@esteemperf.com.sg>

FINALISED SKU2175A

Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
To: jenny chong <jenny@esteemperf.com.sg>

Thu, Apr 16, 2020 at 10:43 AM

Final repair cost at L/Sump\$9400.00 16days confirmed. Kenneth

From: jenny chong <jenny@esteemperf.com.sg>

Sent: Saturday, 11 April 2020 1:57 PM

To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>; Claim admin <Claimadmin@esteemperf.com.sg>

Subject: Re: FINALISED SKU2175A

[Quoted text hidden]



ESTEEM PERFORMANCE PTE LTD

Bik 6033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569636.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKU 2175 A

Finalised

Parts	(a) Cost / List Price Items	\$107130	13,782.90
	Plus/Less 20%	\$217426	2,756.58
	Total of Cost / List	\$869704	11,026.32
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$4000	295.00
	Total Parts Cost	\$873704	11,321.32
	Labour	\$303000	5,750.00
	Total	\$1176704	17,071.32

Not Authorized
Resurvey After Rain
L/Ring @?

L/S \$9,400.00

16 DAYS

The above total will be subjected to 7% G.S.T.

- 20%
= \$9410.00 ✓

Name of Surveyor

Kenneth

Company

ELK

Survey conducted on

4/2/20

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 16 day(s) ✓

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

PC

Date: 4/2/20



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKU 2175 A**
Make & Model : **HONDA ODYSSEY**
Chassis No : **JHMRC1890EC201502**

Submit By : **JENNY**
Year Manufacture : **2014**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>RM</i>	1	\$195.00		<i>✓</i>
2	Rear windscreen sealant <i>RM</i>	1	\$50.00	S.N	<i>4012</i>
3	Reverse sensor <i>RM</i>	1	\$200.00	S.N	<i>X</i>
4	Rear bumper <i>RM</i>	1	\$657.20		<i>✓</i>
5	Rear bumper clip <i>RM</i>	10	\$35.00		<i>✓</i>
6	Rear bumper side retainer LH <i>SVC</i>	1	\$30.00		<i>X</i>
7	Rear bumper side retainer RH <i>RM</i>	1	\$30.00		<i>✓</i>
8	Rear bumper bracket LH <i>SVC</i>	1	N/A		<i>X</i>
9	Rear bumper bracket RH <i>SVC</i>	1	N/A		<i>X</i>
10	Rear bumper sponge <i>SVC</i>	1	N/A		<i>X</i>
11	Rear bumper reinforcement <i>SVC</i>	1	N/A		<i>X</i>
12	Rear bumper reflector RH <i>cracked</i>	1	\$65.40		<i>✓</i>
13	Rear number plate <i>RM</i>	1	\$45.00	S.N	<i>X</i>
14	Tail door <i>RM</i>	1	\$1,293.00		<i>✓</i>
15	Tail door lock <i>RM</i>	1	\$239.00		<i>X</i>
16	Tail door trim <i>RM</i>	1	\$292.30		<i>X</i>
17	Tail door trim clip	10			
18	Tail door reflector LH <i>RM</i>	1	\$428.60		<i>✓</i>
19	Tail door reflector RH <i>RM</i>	1	\$428.60		<i>✓</i>
20	Tail door reflector centre <i>RM</i>	1	\$330.30		<i>X</i>
21	Tail door centre chrome <i>RM</i>	1	\$245.00		<i>✓</i>
22	Tail end panel <i>cat price</i> <i>RM</i>	1	\$551.80		<i>✓</i>
23	Tail end panel garnish <i>RM</i>	1	\$155.00		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4680

845460

Spare Parts

Vehicle No. : **SKU 2175 A**

Make & Model : **HONDA ODYSSEY**

Chassis No. : **JHMRC1890EC201502**

Submit By : **Carmen Lim**

Year Manufacture : **2014**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip SVC	10	N.A		X
25	Boot weatherstrip Sm	1	\$150.90		X
26	Tail lamp LH Sm	1	\$871.80		X
(27)	Tail lamp RH mgc m	1	\$871.80		(27)
28	Spare tyre well panel R	1	\$381.30		X
29	Spare tyre board Sm	1	\$384.10		X
30	Spare tyre compartment sponge LH NN	1	TBA		X
31	Spare tyre compartment sponge RH NN	1	TBA		X
32	Spare tyre compartment centre NN	1	TBA		X
33	RH rear fender Burn	1	\$1,073.70		—
34	RH rear fender undershield Dir	1	\$166.30		—
35	RH rear fender undershield clip Sm	10	\$35.00		—
36	RH rear fender air duct Sm	1	\$45.70		X
(37)	RH rear inner trim mgc m	1	\$899.10		(37)
38	RH rear inner trim clip nn	10	\$45.00		X
39	Air bag roof top LH Burn	1	\$910.70		—
40	Air bag control unit Sm	1	\$1,034.70		—
41	Roof Lining Re turn	1	\$1,041.80		—
42	Roof lining clip Sm	10	\$55.00		—
43	Exhaust pipe Ry	1	\$686.80		—
44	Exhaust pipe mouting Sm	1	\$56.50		X
45	Exhaust insulator Sm	1	\$96.50		X
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

674.90

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SKU 2175 A

HONDA ODYSSEY

JHMRC1890EC201502

Submit By :

Year Manufacture :

Engine No. :

CARMEN LIM

2014

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH REAR BUMPER GARNISH	1	\$76.80		
2	RH RADAR COVER	1	\$60.00		
3	SRS unit	1	480.50		
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

13680



ESTEEM PERFORMANCE PTE LTD

Bk: 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKU 2175 A** Submit By : : **Carmen Lim**
Make & Model : **HONDA ODYSSEY** Year of Manufacture : **2014**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, REAR CHASSIC RH)	\$1,800.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, REAR CHASSIC RH)	\$1,800.00	1000
3	TO Check wiring	\$50.00	20
4	To do wheel alignment. <i>nn</i>	\$120.00	X X
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$250.00	90
7	To remove & refit inner seat & upholstery to assist work load.	\$250.00	120
8	To remove & refit roof lining, inner trim to assist work load.	\$400.00	200
9	To remove & refit exhaust system to assist work load.	\$150.00	60
10	To transfer boot mechanism to new boot	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SKU 2175 A**

Submit By : : **Carmen Lim**

Make & Model : HONDA ODYSSEY

Year of Manufacture : 2014

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.