

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

## **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date 01/10/2020 Reference CC4/FCI20

2 1 E

CC4/FCI20001919/Fda3q2

Code FCI2

AC2006760

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SGE 9079E

Insured Veh. SHA 1370A

Claim No. D20000695MFSH

Policy No. D-20094922MFSH

Accident Date 20/01/2020

Inspection Date 04/02/2020

Description	Total
Survey Inspection	282.00
Digital Photographs	
Transportation	
Subtotal	282.00
GST (7%)	19.74
Grand Total	301.74

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
MS F	FIRST CAPITAL INSURANCE LTD Ref: CC4/FCI20001919/Fda3q2			/Fda3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 01-10-2020 Code: FCI2			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHA 1370A	Veh. Inspected	SGE 9079E	
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
	Claim No.	D20000695MFSH	Excess (\$)	0.00	
	Assign From	MAY CHUA	Assign Date	03/02/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA WISH	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	ZNE100287335	Colour	SILVER	
	Odometer	316450	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	_	Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
	L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
	R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
	L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
4.		•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR O/S AND REAR PORTIO	N.	
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	20/01/2020	Inspection Date	04/02/2020	
	Survey held at	BIFROST AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 9079E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	500.00	-
1	REAR BUMPER RETAINER	NOT NECESSARY	61.00	-
1	REAR BUMPER REVERSE SENSOR (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	65.00	-
1	RH AIR DUCT	NOT NECESSARY	68.00	-
1	RH REAR FENDER INNER TRIM BOARD	NOT NECESSARY	850.00	-
1	RH REAR FENDER	DENTED	950.00	950.00
1	RH REAR FENDER SHIELD	NOT NECESSARY	85.00	-
1	RH REAR DOOR	TO REPAIR SEE LABOUR	1,245.00	-
1	RH REAR DOOR WEATHERSTRIP	NOT NECESSARY	195.00	-
1	RH REAR DOOR LOCK (NPA)	NOT NECESSARY	-	-
1	RH ROCKER PANEL	TO REPAIR SEE LABOUR	400.00	-
1	RH REAR ABSORBER	NOT NECESSARY	215.00	-
1	RH REAR WHEEL HUB BEARING	NOT NECESSARY	715.00	-
1	RH REAR AXLE	NOT NECESSARY	2,315.00	-
1	RH TAIL LAMP	NOT NECESSARY	507.00	-
1	RH TAIL LAMP PANEL	NOT NECESSARY	195.00	-
1	RH REAR MATTFLAT	NOT NECESSARY	900.00	-
4	RH REAR WINDSCREEN MOULDING @\$48.00	NECESSARY	192.00	120.00
	LESS 20% DISCOUNT		-1,891.60	-
	LESS 25% DISCOUNT		-	-267.50
			7,566.40	802.50
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			50.00	-
	LABOUR			
	TO CHECK WIRING AND LIGHTING SYSTEM.		100.00	50.00
	TO R&R REAR BUMPER PARKING SENSOR .		100.00	50.00

Report Ref No. CC4/FCI20001919/Fda3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,350.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIT WINDSCREEN .		150.00	100.00
	TO SUPPLY UNDER-COATING /PUTTY ON PARTS REPLACED .		80.00	30.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT BEFORE & AFTER.		180.00	100.00
	TO R&R REAR RH WHEEL RIM ,TYRE AND BALANCING.		50.00	50.00
	TO R&R REAR RH UNDER CARRIAGE DAMAGED PARTS.		350.00	120.00
	TO REPAIR ,REPLACE & REALIGN DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF RH REAR DOOR ,REAR BUMPER AND RH ROCKER PANEL .		1,200.00	1,000.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	600.00
			3,490.00	2,130.00
	GRAND TOTAL		11,106.40	2,932.50

Report Ref No. CC4/FCI20001919/Fda3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

**HO LEONG CHUAN** 

**Automotive Assessor** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SGE 9079E



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

