

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 5016Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR BASE RH (CONSISTENT)	сит	527.50	527.50
1	FRT FENDER RH (CONSISTENT)	BENT	435.00	435.00
1	FRT FENDER SHIELD RH (CONSISTENT)	DEFORMED	171.50	171.50
12	FRT FENDER SHIELD CLIP @\$3.20 (CONSISTENT)	NECESSARY	38.40	38.40
1	FRT WHEEL KNUCKLE RH (CONSISTENT)	BENT	345.00	345.00
1	FRT WHEEL BEARING RH (CONSISTENT)	BENT	268.00	268.00
1	FRT LOWER ARM RH (CONSISTENT)	NOT NECESSARY	328.00	-
1	FRT SHOCK ABSORBER RH (CONSISTENT)	NOT NECESSARY	482.00	-
1	FRT DOOR RH (CONSISTENT)	BENT	757.50	757.50
1	FRT DOOR OUTER HANDLE RH (CONSISTENT)	NOT NECESSARY	322.70	-
1	FRT DOOR INNER LOCK RH (CONSISTENT)	BENT	375.00	375.00
1	FRT DOOR OUTER MOULDING (CONSISTENT)	NOT NECESSARY	155.00	-
1	FRT DOOR TRIM BOARD RH (CONSISTENT)	CRACKED	782.00	782.00
15	DOOR TRIM BOARD CLIP @\$3.50 (CONSISTENT)	NECESSARY	52.50	52.50
2	FRT DOOR HINGE RH UPPER & LOWER @\$125.00 (CONSISTENT)	BENT	250.00	250.00
1	FRT WINDOW REGULATOR ASSY RH (CONSISTENT)	BENT	482.90	482.90
1	RR DOOR RH (CONSISTENT)	BENT	799.50	799.50
1	RR DOOR TRIM BOARD RH (CONSISTENT)	NOT NECESSARY	823.00	-
15	RR DOOR TRIM BOARD CLIP @\$3.50 (CONSISTENT)	NOT NECESSARY	52.50	-
2	RR DOOR HINGE RH LOWER & UPPER @\$125.00 (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	RR WINDOW REGULATOR ASSY RH (CONSISTENT)	NOT NECESSARY	495.00	-
1	ROCKER PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	415.30	-
1	FRT QUARTER GLASS WITH MOULDING ASSY (CONSISTENT)	NOT NECESSARY	498.00	-
	LESS 20% DISCOUNT		-1,821.26	-1,056.96
			7,285.04	4,227.84
	SPECIAL NETT ITEMS			
1	FRT TYRE RH (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	FRT SPORT RIM RH (SN) (CONSISTENT)	сит	650.00	350.00

Report Ref No. CC4/ASM20001929/T1pa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	CERAMIC COATING PACKAGE (SN) (CONSISTENT)	NECESSARY	980.00	350.00
1	PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	40.00
1	PERFORM WHEEL ALIGNMENT WITH REPORT (BEFORE & AFTER) (SN) (CONSISTENT)	NECESSARY	120.00	80.00
			2,150.00	820.00
	LABOUR			
	TO REMOVE & REINSTALL ITERIOR TRIMS ,GARNISHES ,SEATS ETC FOR NECESSARY REPAIR.		250.00	60.00
	TO CHECK ELECTRICAL WIRING SYSTEM RH.		120.00	30.00
	TO TRANSFER FRT RH DOOR COMPONENT PARTS TO NEW DOOR (INCLUDE WINDOW GLASS & WINDOW BRACKET).		150.00	60.00
	TO TRANSFER RR RH DOOR COMPONENT PARTS TO NEW DOOR (INCLUDE WINDOW GLASS & WINDOW BRACKET).		150.00	60.00
	TO REMOVE & REINSTALL FRT RH UNDERCARRIAGE PARTS FOR REPAIR.		200.00	100.00
	TO STRAIGHTEN ,REPAIR ,REALIGN ON AFFECTED AREA.INCLUSIVE OF THE REPAIR OF RR DOOR HINGE RH LOWER & UPPER AND ROCKER PANEL RH .		1,800.00	800.00
	TO SPRAY PAINTING ON AFFECTED AREA & NEW PARTS.		2,000.00	900.00
	TO APPLY ANTI-RUST COATING ON AFFECTED PANEL.		180.00	50.00
	TO REMOVE & REINSTAL QUARTER GLASS.	NOT NECESSARY	100.00	-
			4,950.00	2,060.00
	GRAND TOTAL		14,385.04	7,107.84

RECOMMENDED COST OF LUMP SUM REPAIRS		5,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20001929/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.