



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004549
INV Date 25/06/2020
Reference CC4/FCI20001948/Kka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 7776Y
Insured Veh. SHC 2987D
Claim No. D20000592MFSH
Policy No. D-20094922MFSH
Accident Date 22/01/2020
Inspection Date 04/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20001948/Kka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-06-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2987D	Veh. Inspected	GBJ 7776Y	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000592MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	04/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFHT02P900249358	Colour	WHITE	
Odometer	13503	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2020	Inspection Date	04/02/2020	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7776Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	386.95	386.95
10	REAR BUMPER CLIP	NECESSARY	32.10	32.10
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	48.70	48.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	48.70	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	44.90	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	44.90	-
	LESS 25% DISCOUNT		-151.56	-116.94
			454.69	350.81
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER ,TAIL DOOR ,END PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH AND REAR BUMPER BRACKET RH.		800.00	200.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(REAR BUMPER ,TAIL DOOR ,END PANEL).		800.00	200.00
	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO TUFF COAT.	NOT NECESSARY	100.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING,	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REVERSE SENSOR .		120.00	50.00
			-	-
			-	-
			-	-
			2,090.00	450.00
	GRAND TOTAL		2,744.69	800.81



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			650.00
---	--	--	--------

Report Ref No. CC4/FCI20001948/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 7776Y

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 776Y

RE-INSPECTION

