

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBJ 7776 Y

Finalized

Parts (a) Cost / List Price Items	\$ 467.75	606.25
Plus/Less 25%	\$ 116.94	151.56
Total of Cost / List	\$ 350.81	454.69
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	200.00
Total Parts Cost	\$	654.69
Labour	\$ 450.00	2,090.00
Total	\$ 800.81	2,744.69

Not Authorized
Murray Bepain
LLP @ 650/-

The above total will be subjected to 7% G.S.T.

20/-
\$640.65

Name of Surveyor : Kenneth
Company : CLK
Survey conducted on : 4/2/20 at

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 02 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$
- (e) Signature of surveyor : Le Date: 4/2/20

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

GBJ 7776 Y

TOYOTA HIACE

JTFHT02P900249358

Submit By : JENNY
Year Manufacture : 2019
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$386.95		✓
3	Rear bumper clip	10	\$32.10		✓
4	Rear bumper side retainer LH	1	\$48.70		✓
5	Rear bumper side retainer RH	1	\$48.70		X
6	Rear bumper bracket LH	1	\$44.90		X
7	Rear bumper bracket RH	1	\$44.90		X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

467-75

Labour

Submit By : Carmen Lim

Year of Manufacture : 2019

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

450