



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 7240G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	785.60	785.60
1	FRONT BUMPER SIDE GARNISH RH (CONSISTENT)	CUT	185.20	185.20
1	FRONT BUMPER LOWER (CONSISTENT)	NOT NECESSARY	597.60	-
1	FRONT BUMPER LIP (CONSISTENT)	NOT NECESSARY	127.30	-
1	FRONT RADIATOR GRILLE (CONSISTENT)	NOT NECESSARY	953.70	-
1	FRONT RADIATOR GRILLE TOP COVER (CONSISTENT)	NOT NECESSARY	108.30	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	256.30	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	788.90	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	288.70	-
1	FRONT BUMPER STIFFENER (CONSISTENT)	NOT NECESSARY	192.50	-
1	FRONT BUMPER RETAINER (CONSISTENT)	NECESSARY	89.60	89.60
1	FRONT FOGLAMPS LOWER COVER RH (CONSISTENT)	NOT NECESSARY	132.60	-
1	FRONT FOGLAMPS UPPER COVER RH (CONSISTENT)	NOT NECESSARY	138.60	-
1	FRONT DAYLIGHT H (CONSISTENT)	NOT NECESSARY	629.50	-
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	NOT NECESSARY	87.90	-
1	FRONT HEADLAMP RH (CONSISTENT)	CRACKED	2,698.50	2,698.50
1	FRONT HEADLAMP BRACKET (CONSISTENT)	CRACKED	95.80	95.80
1	FRONT FOGLAMP RH (CONSISTENT)	NOT NECESSARY	268.50	-
1	FRONT BONNET (CONSISTENT)	NOT NECESSARY	1,852.30	-
1	FRONT BONNET LOCK (CONSISTENT)	NOT NECESSARY	198.20	-
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	1,056.70	-
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	265.80	-
1	FRONT FENDER INNER COWLING RH (CONSISTENT)	NOT NECESSARY	156.30	-
1	FRONT FENDER RH (CONSISTENT)	NOT NECESSARY	966.80	-
1	FRONT FENDER ARCH GARNISH RH (CONSISTENT)	NOT NECESSARY	198.50	-
1	FRONT FOGLAMP CHROME GARNISH RH (TOP) (CONSISTENT)	NECESSARY	120.00	60.00
1	FRONT FOGLAMP CHROME GARNISH RH (BOTTOM) (CONSISTENT)	NECESSARY	120.00	60.00
	LESS 20% DISCOUNT		-2,671.94	-794.94
			10,687.76	3,179.76

Report Ref No. CC4/ASM20001950/Aga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (CONSISTENT) (SN)	NECESSARY	30.00	30.00
1	SET FRONT RADIATOR GRILLE CLIPS (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
1	SET FRONT REVERSE SENSORS (CONSISTENT) (SN)	NOT NECESSARY	250.00	-
1	SET FRONT FENDER COWLING (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER OUTER GARNISH CLIPS (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
			370.00	30.00
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT,WELD ,REALIGN AND ALIGNE ALL PARTS.		1,600.00	300.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	250.00
	TO TUFFCOAT AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE SENSORS AND DISTANCE SETTING.		150.00	50.00
	TO REMOVE AND REFIT CONDENSER /RADIATOR AND TOP UP AIR CON GAS.	NOT NECESSARY	120.00	-
	TO CONDUCT WIRING CHECK ON FRONT HEADLAMPS.		120.00	30.00
			3,790.00	630.00
<b>GRAND TOTAL</b>			<b>14,847.76</b>	<b>3,839.76</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,000.00</b>

Report Ref No. CC4/ASM20001950/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.