



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20001950/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 08-07-2020



ATTN:YVONNE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|--------------|-----------------------|------------|
| Insured Veh. | SHD 5346D | Veh. Inspected | SFS 7240G |
| Policy No. | VFX/P1680520 | Coverage (\$) | 0.00 |
| Claim No. | S0M02F5B | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 04/02/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | HYUNDAI TUCSON | c.c | 1999 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | KMHJ3813MHU292856 | Colour | SILVER |
| Odometer | 73960 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 225/55 R18 | YOKOHAMA | 6 mm |
| L/H Front Tyre | 225/55 R18 | YOKOHAMA | 6 mm |
| R/H Rear Tyre | 225/55 R18 | YOKOHAMA | 6 mm |
| L/H Rear Tyre | 225/55 R18 | YOKOHAMA | 6 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 29/01/2020 | Inspection Date | 04/02/2020 |
| Survey held at | CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|-----------------------|