

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2007439

INV Date 06/11/2020

Reference CC4/FCI20001952/T1ea3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBF 9530Y

Insured Veh. SHD 7178J

Claim No. D20000532MFSH

Policy No. D-20094922MFSH

Accident Date 19/01/2020

Inspection Date 04/02/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 350.00 |
| Subtotal | 350.00 |
| GST (7%) | 24.50 |
| Grand Total | 374.50 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| | Affiliated to Federation Internationale Des Experts En Automobile | | | |
|------|---|---|--------------------------------|------------|
| MS F | RST CAPITAL INSURANCE LTD Ref : CC4/FCl20001952/T1ea3q2 | | | |
| | 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date: 06-11-2020 Code: FCI2 | |
| 1. | | Policy Particulars | - THIRD PARTY CLAIM | |
| | Insured Veh. | SHD 7178J | Veh. Inspected | FBF 9530Y |
| | Policy No. | D-20094922MFSH | Coverage (\$) | 0.00 |
| | Claim No. | D20000532MFSH | Excess (\$) | 0.00 |
| | Assign From | RACHEL WU | Assign Date | 03/02/2020 |
| 2. | | Vehicle Partic | culars & Condition | |
| | Make & Model | HONDA LH125 | c.c | 125 |
| | Engine No. | HIDDEN | Year of Reg. | 2012 |
| | Chassis No. | LALJA11U3C3009628 | Colour | RED |
| | Odometer | 59401 | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. | | Condition | ons of Tyres | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 2.75 R18 | PIRELLI | 5 mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | 3.00 R18 | PIRELLI | 5 mm |
| | L/H Rear Tyre | | | mm |
| 4. | | Description | on of Damages | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE REA | AR PORTION AND N/S BOD | Y |
| | DAMAGES SEE D | ETAILS. | | |
| 5. | | General | Information | |
| | Accident Date | 19/01/2020 | Inspection Date | 04/02/2020 |
| | Survey held at | A.S. PHOON PTE LTD | | |
| | | BLK 36 TOH GUAN ROAD EAST #01-35 . SINGAPORE 608580 | | |
| 5a. | | Re | emarks | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. | Estimate Days of Repair | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9530Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR FENDER | сит | 115.00 | 115.00 |
| 1 | REAR LICENCE PLATE | BENT | 20.00 | 20.00 |
| 1 | REAR LICENCE PLATE LIGHT | CRACKED | 85.00 | 85.00 |
| 1 | STAY ,REAR LICENCE PLATE LIGHT | BENT | 60.00 | 60.00 |
| 1 | EXHAUST ASSY | TO REPAIR SEE LABOUR | 390.00 | - |
| 1 | EXHAUST GASKET | NOT NECESSARY | 8.00 | - |
| 1 | REAR CAP MUFFLER | DENTED | 55.00 | 55.00 |
| 1 | HEAT PROTECTION | CUT | 85.00 | 85.00 |
| 1 | FRONT FENDER | CUT | 78.00 | 78.00 |
| 1 | FRONT SIGNAL LH | CUT | 60.00 | 60.00 |
| 1 | CLUTCH LEVER | CUT | 28.00 | 28.00 |
| 1 | IU UNIT | CUT | 160.00 | 160.00 |
| 1 | IU BRACKET | BENT | 40.00 | 40.00 |
| 1 | HANDLE BAR | NOT NECESSARY | 110.00 | - |
| 1 | FUEL TANK | TO REPAIR SEE LABOUR | 395.00 | - |
| 1 | GEAR PEDAL | BENT | 60.00 | 60.00 |
| 1 | REAR SIGNAL LH | CRACKED | 60.00 | 60.00 |
| 1 | REAR FOOTREST | CUT | 48.00 | 48.00 |
| 1 | REAR FOOTREST BRACKET LH | BENT | 85.00 | 85.00 |
| 1 | REAR TOP BOX | CUT | 250.00 | 250.00 |
| | LESS 10% DISCOUNT | | - | -128.90 |
| | | | 2,192.00 | 1,160.10 |
| | <u>LABOUR</u> | | | |
| | TO RE-ALIGNMENT FRONT FORK . | | 150.00 | 100.00 |
| | WORKMANSHIP .INCLUSIVE OF THE REPAIR OF EXHAUST ASSY AND FUEL TANK. | | 300.00 | 200.00 |
| | TRANSPORTATION TP-IDAC-WORKSHOP . | | 100.00 | 80.00 |
| | BODY CHASSIS REPAIR . | NOT NECESSARY | 280.00 | - |
| | TRANSPORTATION 2 WAY TO REPAIR CHASSIS. | NOT NECESSARY | 100.00 | - |

Report Ref No. CC4/FCI20001952/T1ea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------|-----------|-------------------------------|-------------------|
| | SPRAY PAINTING. | | 350.00 | 200.00 |
| | | | 1,280.00 | 580.00 |
| | GRAND TOTAL | | 3,472.00 | 1,740.10 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 1,400.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CC4/FCI20001952/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 9530Y

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 9530Y

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315



