



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 7377Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR (CONSISTENT)	BENT	1,006.50	1,006.50
1	REAR TYRE COVER (CONSISTENT)	BROKEN	675.60	675.60
1	REAR BUMPER (CONSISTENT)	DEFORMED	421.30	421.30
1	REAR REFLECTOR LH (CONSISTENT)	SERVICEABLE	55.30	-
1	REAR REFLECTOR RH (CONSISTENT)	SERVICEABLE	55.30	-
1	REAR TAIL LIGHT LH (CONSISTENT)	SERVICEABLE	231.60	-
1	REAR TAIL LIGHT RH (CONSISTENT)	SERVICEABLE	231.60	-
1	REAR PANEL (CONSISTENT)	BENT	655.10	655.10
	LESS 25% DISCOUNT		-	-689.63
			3,332.30	2,068.87
SPECIAL NETT ITEMS				
1	NUMBER PLATE (CONSISTENT)(SN)	CRACKED	30.00	30.00
1	NUMBER PLATE HOLDER (CONSISTENT)(SN)	DEFORMED	25.00	25.00
			55.00	55.00
LABOUR				
	LABOUR TO DISMANTLE & INSTALL WITH GLASS.		1,200.00	850.00
	SPRAY PAINTING.		1,000.00	800.00
			2,200.00	1,650.00
GRAND TOTAL			5,587.30	3,773.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC4/ASM20001955/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.