

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001957/BEA3Q2

Date: 20/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700009596

Claimant
Vehicle No : SJD9924K **Insured Vehicle No :** SGY1762M

Date of Loss: 31/01/2020 Nature of Claim: TP Claim No: 3918197656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD9924K		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4038740
Reg. Date:	11/04/2008 (Man. Year: 2008)	Chassis No:	GE61034231
Colour:	Black	Odometer:	170502 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,863.92	4,066.64	4,797.28	54.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	2,230.00	2,090.00	48.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,183.92	6,296.64	6,887.28	52.24
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	13,183.92	5,000.00	8,183.92	62.08
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,007.45		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 04/02/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	984.20 FL	*796.60 FL
2	1		*TAILGATE LOGO	Necessary	95.40 FL	*42.00 FL
3	1		*TAILGATE INNER LOCK	Jammed	288.60 FL	*232.40 FL
4	1		*TAILGATE STRIKER	Not Damaged	48.90 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Torn	165.60 FL	*165.60 FL
6	1		*TAILGATE INNER TRIM BOARD	Dislodged	296.30 FL	*192.30 FL
7	1		*TAILGATE INNER HANDLE	Not Damaged	36.00 FL	*- FL
8	1		*TAILGATE OUTER GARNISH	Cut	198.00 FL	*120.60 FL
9	2		*TAILGATE NO PLATE LAMP	Not Damaged	177.00 FL	*- FL
10	1		*TAILGATE SOLENOID SWITCH	Not Damaged	235.00 FL	*- FL
11	1		*TAILGATE WINDSCREEN	Not Damaged	1,124.00 FL	*- FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	90.50 FL	*90.50 FL
13	1		*REAR BUMPER	Dented	856.90 FL	*566.30 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	97.20 FL	*97.20 FL
15	2		*REAR BUMPER BRACKET	No such part	79.20 FL	*- FL
16	1		*REAR END PANEL	Dented	525.60 FL	*422.50 FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	124.80 FL	*124.80 FL
18	1		*REAR BUMPER LOWER LID	No such part	368.00 FL	*- FL
19	2		*REAR BUMPER REFLECTOR	No such part	388.00 FL	*- FL
20	3		*REAR LOWER LID GARNISH	No such part	195.00 FL	*- FL
21	1		*TAILLAMP RH	Broken	684.50 FL	*610.00 FL
22	1		*TAILLAMP LOWER BRACKET RH	No such part	87.00 FL	*- FL
23	1		*TAILLAMP LH	Broken	684.50 FL	*610.00 FL
24	1		*TAILLAMP BRACKET LH	No such part	87.00 FL	*- FL
25	1		*EXHAUST PIPE	Not Damaged	728.20 FL	*- FL
26	2		*EXHAUST PIPE MOUNTING	Not Damaged	116.00 FL	*- FL
27	1		*EXHAUST PIPE HEAT SHIELD	Not Damaged	156.00 FL	*- FL
28	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
29	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*TAILGATE WINDSCREEN CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*TAILGATE PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR NO PLATE WITH COVER	Bent	80.00 FS	*50.00 FS
35	2		*REAR BUMPER REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
36	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*REVERSE CAMERA	Cut	350.00 FS	*250.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
39	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
41	2		*TAILLAMP INNER SEAL	Not Necessary	160.00 FS	*- FS
42	1		*TOWING CAP	Dislodged	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,647.40	4,880.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,783.48	814.16
Total Parts (\$\$)	8,863.92	4,066.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	100.00	80.00
2	R&R REAR WINDSCREEN	New	250.00	120.00
3	R&R EXHAUST PIPE ASSY	New	250.00	0.00
4	R&R REVERSE SENSOR WITH DRILL HOLE IN BUMPER	New	120.00	60.00
5	R&R REVERSE CAMERA	New	150.00	60.00
6	DISCONNECT WIRE HARNESS TO FACILITATE REPAIR ,RECONNECT AND CHECK FUNCTION	New	100.00	50.00
7	PANEL BEAT	New	1,600.00	1,000.00
8	RUST PROOFING	New	150.00	60.00
9	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			4,320.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >