

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001959/GDA3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SME418Z **Insured Vehicle No :** SLZ7309K

Date of Loss: 03/02/2020 **Nature of Claim:** TP **Claim No:** 5486452112SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME418Z		
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Engine No:	CYG023783
Reg. Date:	10/08/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4G4JN046604
Colour:	Black	Odometer:	30932 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,577.00	11,285.44	13,291.56	54.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,212.00	3,302.00	2,910.00	46.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	30,789.00	14,587.44	16,201.56	52.62
+ GST 7.00/7.00% (\$\$)	2,155.23	1,021.12	1,134.11	52.62
Nett Amount (\$\$)	32,944.23	15,608.56	17,335.67	52.62
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		16,010.56		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,877.00 FS	*2,301.60 FS
2	1		*FRONT BUMPER GRILLE -LOWER CENTRE	Not Necessary	120.00 FS	*- FS
3	14		*LOCKING CLIP	Not Necessary	52.00 FS	*- FS
4	1		*FRONT BUMPER FIXING PARTS	Not Necessary	511.00 FS	*- FS
5	1		*FRONT BUMPER ADAPTER LH	Not Necessary	36.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	N/S Missing / O/S NotNecessary	537.00 FS	*429.60 FS
7	1		*FRONT BUMPER COVER -LH	Not Necessary	48.00 FS	*- FS
8	1		*FRONT PARKING SENSOR -OUTER (NPA)	Not Necessary	0.00 FS	*- FS
9	1		*DISTANCE REGULATION CONTROL UNIT	Not Necessary	5,553.00 FS	*- FS
10	1		*RADAR SENSOR COVER FRAME	Not Necessary	12.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE PIECE LH	Deformed	36.00 FS	*28.16 FS
12	1		*FRONT BUMPER BRACE -LH	Not Necessary	28.00 FS	*- FS
13	1		*FRONT FENDER -LH	Buckled	1,310.00 FS	*1,048.00 FS
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	97.00 FS	*- FS
15	1		*STONE GUARD FILM -LH	Necessary	114.00 FS	*90.80 FS
16	1		*FRONT FENDER BRACE -LH	Bent	90.00 FS	*71.92 FS
17	1		*WHEEL HOUSING LINER -LH	Not Necessary	259.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	69.00 FS	*- FS
19	1		*FRONT WHEEL SPOILER -LH	Cracked	249.00 FS	*199.20 FS
20	1		*LED HEADLIGHT -LH	Cracked	8,888.00 FS	*7,110.40 FS
21	1		*HEADLIGHT MOUNTING -LH	Not Necessary	112.00 FS	*- FS
22	1		*TURN SIGNAL POWER MODULE	Not Necessary	532.00 FS	*- FS
23	1		*DIPPED BEAM POWER MODULE	Not Necessary	524.00 FS	*- FS
24	2		*HEADLAMP ASSEMBLY SPACER	Not Necessary	79.00 FS	*- FS
25	1		*HEADLAMP ADJUSTMENT ELEMENT	Not Necessary	43.00 FS	*- FS
26	1		*LIFT CYLINDER -L	Not Necessary	223.00 FS	*- FS
27	1		*HEADLIGHT WASHER COVER CAP -LH	Not Necessary	54.00 FS	*- FS
28	1		*FRONT ALUMINIUM RIM -LH	Not Necessary	741.00 FS	*- FS
29	1		*WHEEL HUB	Not Necessary	441.00 FS	*- FS
30	1		*WHEEL BEARING	Not Necessary	542.00 FS	*- FS
31	1		*SUNDRIES	Necessary	400.00 FS	*5.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 24,577.00 11,285.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND HEADLIGHT .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,900.00	1,100.00
4	TO RENEW LHS FRONT ACC CONTROL UNIT AND CARRY OUT CALIBRATION	New	280.00	280.00
5	TO RENEW LHS FRONT WHEELHUB AND BEARING	New	280.00	0.00
6	TO RENEW LHS FRONT RIM ,CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,212.00	3,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >