Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001969/R1KA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant GBF5476Y Insured Vehicle No: SMJ6663R

Date of Loss: 30/01/2020 Nature of Claim: TP Claim No: 0371170778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF5476Y

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2623948

Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: JTFAT35Y60K206575

Colour: Grey Odometer: 57693 km

Engine Capacity: 2982 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 195/75 R15 (D)
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 5/5 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,973.25	2,644.00	2,329.25	46.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,400.00	1,380.00	49.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,753.25	4,044.00	3,709.25	47.84
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	7,753.25	3,200.00	4,553.25	58.73
+ Loss of Use (7.0 x S\$8	30.00/day) (S\$)	560.00		
+ Doc/S	2.00			
Net	tt Liability (S\$)	3,762.00		
Global Sum S	Settlement (S\$)	3,760.00		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 06/02/2020 Inspected At: C L Auto Pte Ltd (HQ)

48 Toh Guan Road East, #02-125

Enterprise Hub

Singapore 608586

6.0 days

Estimated Period of Repair:

Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*DYNA STICKER	Necessary	20.00 FS	*10.00 FS		
2	4		*BACK DOOR HINGES	Bent (3 PCS ONLY)	480.00 F	*360.00 FN		
3	1		*BACK DOOR LOCK RH	Bent	160.00 F	*160.00 FN		
4	1		*BACK DOOR STOPPER RH	Cut	90.00 F	*90.00 FN		
5	1		*REAR FLOOR BOARD SUB-FRAME	Serviceable	800.00 FS	*- FS		
6	1		*BACK DOOR STICKER -13 PAX	Necessary	12.00 FS	*10.00 FS		
7	1		*BACK DOOR STICKER -70KM/H	Necessary	12.00 FS	*10.00 FS		
8	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS		
9	1		*SET REVERSE SENSORS	Shorted	280.00 FS	*220.00 FS		
10	1		*SET REVERSE CAMERA	Cut	300.00 FS	*150.00 FS		
11	1		*BACK DOOR	Bent	2,162.00 FL	*1,700.00 FL		
12	1		*BACK DOOR TOYOTA STICKER	Necessary	189.00 FL	*189.00 FL		
13	1		*REAR LAMP RH	Scratched	189.00 FL	*189.00 FL		
14	1		*REAR LAMP BRACKET RH	Bent	112.00 FL	*112.00 FL		
15	1		*REAR NUMBER PLATE LAMP	Serviceable	90.00 FL	*-FL		
16	1		*NUMBER PLATE BASE	Bent	132.00 FL	*132.00 FL		
17	1		*EXHAUST TAIL -PIPE	Repair	760.00 FL	*-FL		
18	1		*EXHAUST TAIL -PIPE MOUNTING	Serviceable	65.00 FL	*-FL		
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc. N=NettItemDisc.					
				Sub Total (S\$)	5,898.00	3,377.00		
- List Item Discount on L Items 25.00/25.00% (S\$)				924.75	580.50			
- Nett Item Discount on N Items 0.00/25.00% (S\$)					0.00	152.50		
				Total Parts (S\$)	4,973.25	2,644.00		
	Report was unsubmitted during this print-out.							
L	. 3 1							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE & REFIT REAR BACK DOOR ,REAR RH TAILLAMP & BRACKETS & NO PLATE BASE CUT/WELD REAR FLOOR BOARD SUB-FRAME	New	1,400.00	600.00					
2	TO SPRAY PAINT BACK DOOR ,REAR FLOOR BOARD SUB-FRAME NO PLATE BASED & TAILLAMP BRACKETS	New	900.00	600.00					
3	RUST PROOFING	New	180.00	60.00					
4	TO REMOVE & REFIT REAR EXHAUST PIPE SILENCER	New	120.00	60.00					
5	TO CHECK WIRING & CHECKING REAR REVERSE SENSOR AND CAMERA	New	180.00	80.00					
	Gross Labour Cost (S\$)		2,780.00	1,400.00					

< END OF ESTIMATES >

Report was unsubmitted during this print-out.