

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001979/KDA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLB7958M **Insured Vehicle No :** SLL5371R

Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: 0897401003SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7958M		
Make & Model:	TOYOTA WISH, 1.8 X CVT (A)	Engine No:	2ZR1728464
Reg. Date:	22/04/2016 (Man. Year: 2016)	Chassis No:	ZGE206030123
Colour:	Metallic Pearl White	Odometer:	100255 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,804.10	3,645.55	158.55	4.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,690.00	270.00	13.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,764.10	5,335.55	428.55	7.43
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	5,764.10	4,250.00	1,514.10	26.27
+ GST 7.00/7.00% (S\$)	403.49	297.50	105.99	26.27
Nett Amount (S\$)	6,167.59	4,547.50	1,620.09	26.27
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		5,395.50		
Global Sum Settlement (S\$)		5,390.00		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 04/02/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	491.90 FL	*491.90 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Cracked	89.90 FL	*89.90 FL
3	1		*REAR BUMPER LH CORNER RETAINER	Distorted	40.40 FL	*40.40 FL
4	1		*REAR BUMPER LH REINFORCEMENT BRACKET	Repair	48.44 FL	*- FL
5	5		*REAR BUMPER CLIP	Necessary	17.50 FL	*17.50 FL
6	1		*REAR TAILGATE	Bent	1,175.00 FL	*1,175.00 FL
7	1		*TAILGATE INNER LOCK	Dented	301.60 FL	*301.60 FL
8	1		*TAILGATE INNER RUBBER (50%)	Cut	226.95 FS	*151.30 FS
9	1		*TAILGATE OUTER CHROME	Cracked	301.60 FL	*301.60 FL
10	1		*TAILGATE LOGO	Necessary	66.15 FL	*66.15 FL
11	1		*TAILGATE EMBLEM VALVE MATIC	Necessary	35.49 FL	*35.49 FL
12	1		*TAILGATE LH NO PLATE LAMP	Serviceable	62.10 FL	*- FL
13	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	97.20 FL	*97.20 FL
14	1		*TAILGATE LH REFLECTOR	Cut	294.10 FL	*294.10 FL
15	1		*LH TAILLAMP	Cut	354.70 FL	*354.70 FL
16	1		*REAR END PANEL	Bent	453.90 FL	*453.90 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Mtg Distorted	253.19 FL	*253.19 FL
18	1		*REAR END PANEL ANTENNA	Cracked	144.20 FL	*144.20 FL
19	1		*REAR LH TOOL SPONGE	Cracked	175.50 FL	*175.50 FL
20	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,904.82	4,718.63
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,100.72	1,073.08
Total Parts (\$\$)	3,804.10	3,645.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS PARKING SENSORS ,TAILGATE & ATTACHMENTS ,TAILLAMPs ,TO CUT ,WELD & RENEW REAR END PANEL,KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	New	800.00	700.00
3	PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS ,TAILGATE ,REAR END PANEL ,REAR LUGGAGE PANEL ,REAR LH FENDER & ALL AFFECTED AREAS	New	800.00	700.00
4	REMOVE & REFIX REAR GARNISHS ,SEATS TO FACILITATE REPAIR	New	100.00	60.00
5	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	50.00
6	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (\$\$)			1,960.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >