

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924

INV Date Reference

INV No.

AC2004194

28/05/2020

CS/AGI20001997/Atf3n2

Code

#### PROFESSIONAL SERVICE FEE

Vehicle No. SGR 8181E

Insured Veh. SJM 2583J

Claim No. C10005428

Policy No.

Accident Date 29/01/2020

Inspection Date 05/02/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R							
	Affiliated to Federation Internationale Des Experts En Automobile							
AUT	TO & GENERAL INSURANCE (S) PL Ref : CS/AGI20001997/Atf3n2							
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date: 28-05-2020						
			Code: AGI					
1.	•	Policy Particulars	:- THIRD PARTY CLAIM					
	Insured Veh.	SJM 2583J	Veh. Inspected	SGR 8181E				
	Policy No.		Coverage (\$)	0.00				
	Claim No.	C10005428	Excess (\$)	0.00				
	Assign From	IVY RATILLA	Assign Date	05/02/2020				
2.		Vehicle Partic	culars & Condition					
	Make & Model	OPEL INSIGNIA	c.c	1598				
	Engine No.	HIDDEN	Year of Reg.	2016				
	Chassis No.	W0LGS5E58H1015733	Colour	WHITE				
	Odometer	43884	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	245/45 R18	BRIDGESTONE	6 mm				
	L/H Front Tyre	245/45 R18	BRIDGESTONE	6 mm				
	R/H Rear Tyre	245/45 R18	BRIDGESTONE	6 mm				
	L/H Rear Tyre	245/45 R18	BRIDGESTONE	6 mm				
4.		•	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT O/S PORTION.					
	DAMAGES SEE D							
5.	General Information							
	Accident Date	29/01/2020	Inspection Date	05/02/2020				
	Survey held at	1ST AUTOWORKS PTE LTD						
		23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 8181E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	DISTORTED	1,500.00	1,500.00
1	FRT BUMPER GUIDE LEFT	NECESSARY	30.00	30.00
1	FRT BUMPER SUPPORT LEFT	NECESSARY	45.00	45.00
1	FRT FENDER LH	TO REPAIR SEE LABOUR	570.00	-
1	FRT FENDER LINER LH	NOT NECESSARY	120.00	-
1	FRT HEADLIGHT LH	CRACKED	980.00	980.00
1	FRT FOG LAMP LH	NOT NECESSARY	230.00	-
1	FRT BUMPER ABSORBER,IMPACT,LOWER	NOT NECESSARY	140.00	-
1	FRT BUMPER ABSORBER,IMPACT	NOT NECESSARY	450.00	-
1	FRT BUMPER CENTRE SUPPORT	CRACKED	55.00	55.00
1	RH INSERT	CRACKED	230.00	230.00
1	LH INSERT	NOT NECESSARY	230.00	-
1	FLAP,TOWING LUG,FRT BUMPER	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-467.00	-284.00
			4,203.00	2,556.00
	SPECIAL NETT ITEMS			
1	SET FRT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF FRT FENDER LH.		2,800.00	650.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.(FRT BUMPER & FRT RH FENDER).		2,500.00	550.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		150.00	50.00
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO CONDUCT HEAD LIGHT ALIGNMENT.	NOT NECESSARY	130.00	
			5,760.00	1,250.00

Report Ref No. CS/AGI20001997/Atf3n2



Page No.:2 of 2

GRAND TOTAL	10,013.00	3,856.00
RECOMMENDED COST OF REPAIRS		3.856.00

Report Ref No. CS/AGI20001997/Atf3n2



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SGR 8181E

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SGR 8181E

### RE-INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SGR 8181E

RE-INSPECTION





