

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20002000/T1QF3E2

**Date:** 22/06/2020

### REFERENCE

Insured/Claimant:	PREMIUM LEASING PTE LTD	Policy No:	0999994015
Date of Loss:	16/01/2020	Nature of Claim:	OD Claim No: 3845204662SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7242X		
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Engine No:	CHZ300978
Reg. Date:	15/06/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA6HA022118
Colour:	Grey	Odometer:	14395 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,469.00	290.00	7,179.00	96.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	2,072.00	8,280.00	79.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,821.00</b>	<b>2,362.00</b>	<b>15,459.00</b>	<b>86.75</b>
<b>- Excess (\$\$)</b>	<b>1,200.00</b>	<b>1,200.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>16,621.00</b>	<b>1,162.00</b>	<b>15,459.00</b>	<b>93.01</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,163.47</b>	<b>81.34</b>	<b>1,082.13</b>	<b>93.01</b>
<b>Nett Amount (\$\$)</b>	<b>17,784.47</b>	<b>1,243.34</b>	<b>16,541.13</b>	<b>93.01</b>

### INSPECTION

Date of Assignment:	05/02/2020	
Date Inspected:	04/02/2020	Inspected At: 281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,152.00 NETT)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TOP BUMPER	Repair	1,108.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	73.00 FS	*- FS
3	1		*REAR MIDDLE BUMPER	Not Necessary	733.00 FS	*- FS
4	1		*WHEEL HOUSING LINER TRIM - LH	Not Necessary	26.00 FS	*- FS
5	1		*REAR BUMPER SPOILER - LH	Not Necessary	545.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR - LH	Not Necessary	28.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	51.00 FS	*- FS
8	2		*REAR WHEEL COVER - LH / RH	* Check	852.00 FS	*- FS
9	1		*REAR DOOR - LH (DENTED)	Not Consistent With The Impact	2,380.00 FS	*- FS
10	1		*BONDING AGENT	Not Necessary	46.00 FS	*- FS
11	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
12	1		*REAR DOOR CATCH	Not Necessary	113.00 FS	*- FS
13	1		*REAR DOOR COVER - LH	Cut	290.00 FS	*290.00 FS
14	1		*EXTERIOR MIRROR MOUNTING (CUT)	Not Consistent With The Impact	485.00 FS	*- FS
15	1		*MIRROR CAP - LH (CUT)	Not Consistent With The Impact	159.00 FS	*- FS
16	1		*SUNDRIES	* Check	300.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
18	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	127.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **7,469.00**      **290.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK AND POWER WINDOW DEVICES	New	280.00	0.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR MOUNTING	New	400.00	0.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
5	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, DOOR COVER, DOOR HANDLE, LHS REAR FENDER AND BOTH REAR WHEEL ARCH TRIMS	New	6,400.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,352.00</b>	<b>2,072.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >