

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002003/UDA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SGA2228J **Insured Vehicle No :** SKP8997G

Date of Loss: 25/01/2020 Nature of Claim: TP Claim No: 7225522419SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGA2228J**

Make & Model: HONDA ACCORD, 2.0 (A) Engine No: K20A6530424

Reg. Date: 16/05/2006 (Man. Year: 2006) Chassis No: CL71200421

Colour: Silver Odometer: 187791 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45Z R17 Rear Tyre Size: 235/45Z R17

Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,698.40	2,577.20	2,121.20	45.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,300.00	1,700.00	56.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,698.40	3,877.20	3,821.20	49.64
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	7,698.40	3,100.00	4,598.40	59.73
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		3,820.00		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 05/02/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
 130 Bedok Reservoir Road, Eunoss
 Spring, #08-1339
 Singapore 470130

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Badly Dented / Dented	987.00 FL	*987.00 FL
2	1		*FRONT RH OUTER DOOR HANDLE GARNISH	Scratched	390.00 FL	*285.50 FL
3	1		*FRONT RH OUTER DOOR HANDLE GARNISH CAP	Not Necessary	112.00 FL	*- FL
4	1		*FRONT RH DOOR INNER LOCK	Not Necessary	286.00 FL	*- FL
5	1		*FRONT RH DOOR INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
6	1		*FRONT RH DOOR WEATHER STRIP	Not Necessary	295.00 FL	*- FL
7	1		*FRONT RH DOOR STICKER	Necessary	165.00 FL	*165.00 FL
8	1		*CENTRE DOOR INNER PILLAR RH	Repair	986.00 FL	*- FL
9	2		*REAR RH DOOR	Dented / Bent	897.00 FL	*897.00 FL
10	2		*REAR RH DOOR HINGE (TOP)	Not Necessary	48.00 FL	*- FL
11	1		*REAR RH DOOR HINGE (BOTTOM)	Not Necessary	46.00 FL	*- FL
12	1		*REAR RH DOOR LINKAGE	Not Necessary	55.00 FL	*- FL
13	1		*REAR RH DOOR INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*REAR RH DOOR WEATHER STRIP	Not Necessary	275.00 FL	*- FL
15	1		*SET REAR RH DOOR QUARTER GLASS MOULDING SEAL	Not Necessary	324.00 FL	*- FL
16	1		*REAR RH DOOR STICKER	Necessary	155.00 FL	*155.00 FL
17	1		*RIGHT ROCKER GARNISH	Deformed / Torn	672.00 FL	*672.00 FL
18	1		*RIGHT ROCKER GARNISH CLIPS	Necessary	60.00 FL	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,873.00	3,221.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,174.60	644.30
Total Parts (\$)	4,698.40	2,577.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,200.00	400.00
2	TO PUTYY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,000.00	700.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL FRONT RH DOOR COMPONENTS	New	200.00	60.00
5	TO REMOVE & INSTALL REAR RH DOOR COMPONENTS	New	200.00	60.00
6	TO REMOVE & INSTALL REAR RH DOOR QUARTER GLASS	New	150.00	0.00
7	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,000.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >