



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005437
INV Date 06/08/2020
Reference CC4/FCI20002006/Uea3n2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. PA 8493M
Insured Veh. SHD 3238X
Claim No. D20000463MFSH
Policy No. D-20094922MFSH
Accident Date 16/01/2020
Inspection Date 04/02/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI20002006/Uea3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-08-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3238X	Veh. Inspected	PA 8493M	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000463MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	04/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KDH2230019638	Colour	WHITE	
Odometer	357162	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2020	Inspection Date	04/02/2020	
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8493M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	GRAZED	933.70	699.10
2	REAR BUMPER SIDE RETAINER @\$132.00	NOT NECESSARY	264.00	-
2	REAR BUMPER BRACKET @\$98.00	NOT NECESSARY	196.00	-
1	REAR BUMPER CORNER RH	TO REPAIR SEE LABOUR	175.00	-
1	REAR BUMPER IMPACT BRACKET RH	NOT NECESSARY	193.00	-
1	REAR BUMPER CLIPS	NECESSARY	60.00	50.00
1	REAR TAILLAMP RH	SCRATCHED	994.80	386.40
1	REAR TAILGATE	NOT NECESSARY	2,150.00	-
1	REAR TAILGATE LOGO	NOT NECESSARY	98.00	-
1	REAR TAILGATE EMBLEM (HIACE)	NOT NECESSARY	72.00	-
1	REAR TAILGATE EMBLEM (GL)	NOT NECESSARY	68.00	-
1	REAR TAILGATE GLASS INNER SPONGE SEAL	NOT NECESSARY	98.00	-
1	REAR TAILGATE INNER TRIMBOARD	NOT NECESSARY	245.70	-
1	REAR TAILGATE INNER TRIMBOARD CLIPS	NOT NECESSARY	60.00	-
1	REAR TAILGATE LOCK	NOT NECESSARY	482.50	-
1	REAR END PANEL INNER	NOT NECESSARY	685.00	-
1	REAR END PANEL OUTER	NOT NECESSARY	672.00	-
1	REAR EXHAUST END PIPE	NOT NECESSARY	942.00	-
2	REAR EXHAUST MOUNTING @\$68.00	NOT NECESSARY	136.00	-
1	REAR RH SIDE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 25% DISCOUNT			-2,131.43	-283.88
			6,394.27	851.62
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE ADVERTISEMENT STICKER (SN)	NOT NECESSARY	450.00	-
1	REAR TAILGATE STICKER 70KM (SN)	NOT NECESSARY	45.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE W/GARNISH (SN)	NOT NECESSARY	80.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			1,015.00	-
	LABOUR			
	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIRO REAR BUMPER CORNER RH AND REAR RH SIDE PANEL .		1,200.00	300.00
	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS.		1,400.00	300.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING .		80.00	20.00
	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH .	NOT NECESSARY	150.00	-
	TO REMOVE & INSTALL REAR LEFT FENDER TRIM ,GARNISH .	NOT NECESSARY	150.00	-
	TO REMOVE & INSTALL REAR TAILGATE GLASS .	NOT NECESSARY	200.00	-
	TO REMOVE & INSTALL REAR EXHAUST PIPE .	NOT NECESSARY	150.00	-
	TO RE-POSITION ,DRILL & INSTALL REVERSE SENSOR .		150.00	40.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	200.00	-
			3,830.00	660.00
GRAND TOTAL			11,239.27	1,511.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CC4/FCI20002006/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8493M

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8493M

RE-INSPECTION

