

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Mar 2020 11:54		10 Feb 2020 10:39 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: LION CITY RENTALS PTE LTD									
Vehicle Reg. No.: SLQ7365U		Date of Loss: 29/01/2020 12:00 - :59 [30 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): CB6962M		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Lion City Rentals Pte Ltd () 1090 LOWER DELTA ROAD #05-12, 169201 Bukit Merah - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/02/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ7365U
[CB6962M]
TP
LION CITY RENTALS PTE LTD
Jan 29 2020 12:00PM
[-]
Lion City Rentals Pte Ltd

Upload Documents

Upload Photos























Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/02/20 13:39	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
19	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/02/20 13:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/02/20 13:39	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
22	22/02/20 13:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
23	22/02/20 13:40	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
24	22/02/20 13:40	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002011/ESD3E2

Date: 31/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SLQ7365U

Insured Vehicle No : CB6962M

Date of Loss: 29/01/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7365U

Make & Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5926852

Reg. Date: 20/07/2017 (Man. Year: 2016)

Chassis No: RU31226838

Colour: Black

Odometer: 187006 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm

Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,784.00	2,322.00	462.00	16.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	950.00	600.00	38.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,334.00	3,272.00	1,062.00	24.50
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	4,334.00	2,600.00	1,734.00	40.01
+ GST 7.00/7.00% (S\$)	303.38	182.00	121.38	40.01
Nett Amount (S\$)	4,637.38	2,782.00	1,855.38	40.01

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 05/02/2020 Inspected At:

60 JALAN LAM HUAT# 04-35/36

Repairer : Lion City Rentals Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7365U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	955.00 FL	*850.00 FL
2	1		*F/R FENDER WHEEL ARCH MOULDING	Broken	300.00 FL	*195.00 FL
3	1		*F/R HEADLAMP ASSY	Cut	2,100.00 FL	*1,820.00 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
					Sub Total (S\$)	3,455.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	671.00
					Total Parts (S\$)	2,784.00
						2,322.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PART	New	750.00	450.00
2	TO RESPRAY FRONT BUMPER AND F/R FENDER WHEEL ARCH MOULDING	New	800.00	500.00
Gross Labour Cost (S\$)			1,550.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >