Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002016/UGA3Q2

Date: 29/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498598

Claimant
Vehicle No: GBD9996Y

Insured Vehicle No: SLK5477A

Date of Loss: 03/02/2020 Nature of Claim: TP Claim No: 5892494783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD9996Y

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2411591

Reg. Date: 01/07/2014 (Man. Year: 2014) Chassis No: JTFAT35Y60K203174

Colour: White Odometer: 132509 km

Engine Capacity: 2982 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6/6 mm
Front Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,150.00	2,492.30	3,657.70	59.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,360.00	1,090.00	44.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,600.00	3,852.30	4,747.70	55.21
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	8,600.00	3,050.00	5,550.00	64.53
+ Loss of Use (5.0 x S\$1	00.00/day) (S\$)	500.00		
+ Doc/S	Search Fee (S\$)	36.45		
Ne	ett Liability (S\$)	3,586.45		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 06/02/2020 Inspected At: Zoom Autowerks Pte Ltd (HQ)

Global Sum Settlement (S\$)

130 Bedok Reservoir Road, Eunos

Spring, #08-1339 Singapore 470130

3,550.00

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Dented / Bent	1,945.20 FL	*1,645.10 FL	
2	2		*REAR TAILGATE LATCH	Repair	390.00 FL	*- FL	
3	2		*REAR TAILGATE SIDE MEMBER WITH BUS	Repair	536.00 FL	*- FL	
4	2		*REAR TAILGATE HINGES	Not Necessary	136.00 FL	*- FL	
5	1		*REAR TAILGATE LOWER MEMBER	Bent	749.40 FL	*566.10 FL	
6	1		*TAILLAMPS	O/S Cracked	750.00 FL	*250.20 FL	
7	1		*TAILLAMPS BRACKET	Not Necessary	238.40 FL	*- FL	
8	1		*REAR NUMBER PLATE BRACKET	Bent	155.00 FL	*155.00 FL	
9	1		*REAR NUMBER PLATE LAMP	Not Necessary	175.00 FL	*- FL	
10	1		*REAR TYRE CARRIER	Not Necessary	385.00 FL	*- FL	
11	1		*REAR END STEP PANEL	Bent	680.00 FS	*250.00 FS	
12	1		*SET REAR REVERSE SENSOR	Shorted	750.00 FS	*200.00 FS	
13	1		*REAR DYNA STICKER	Necessary	70.00 FS	*45.00 FS	
14	1		*13 PAX STICKER	Necessary	35.00 FS	*10.00 FS	
15	1		*70KM/H STICKER	Necessary	35.00 FS	*10.00 FS	
16	1		*REAR ADVERTISEMENT STICKER	Not Necessary	450.00 FS	*- FS	
17	1		*REAR NUMBER PLATE	Bent	35.00 FS	*15.00 FS	
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	7,515.00	3,146.40	
- List Item Discount on L Items 25.00/25.00% (S\$) 1,365.00 654						654.10	
				Total Parts (S\$)	6,150.00	2,492.30	
Г	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	680.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,000.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	200.00	50.00
	Gross Labo	Gross Labour Cost (S\$)		1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >