



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 3577G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	HANDLE BAR	O/S NOT NECESSARY / N/S BENT	235.00	117.50
1	HANDLE BAR STABILIZER	BENT	185.00	185.00
1	VISOR	NOT NECESSARY	235.00	-
1	FRONT HEAD COWLING -PANEL	BROKEN	235.00	235.00
1	HEAD LAMP ASSY	BROKEN	550.00	550.00
1	HEAD LAMP STAY	BENT	250.00	250.00
1	SET MIRROR	CUT	220.00	220.00
1	FRONT MUDGUARD	BROKEN	255.00	255.00
2	FRONT SIGNAL	N/S DISTORTED / O/S NOT NECESSARY	180.00	90.00
1	BRAKE LEVER	NOT NECESSARY	68.00	-
1	FRONT L/RH SIDE FAIRING	CRACKED / BROKEN	310.00	310.00
1	FORK TUBE	BENT	480.00	480.00
1	FORK UNDER BRACKET	DAMAGED	220.00	220.00
1	FRONT RIM	DISTORTED	350.00	350.00
1	FRONT BRAKE DISC	NOT NECESSARY	235.00	-
1	FRONT DIMMER LIGHT	CRACKED	235.00	235.00
1	PETROL TANK	TO REPAIR SEE LABOUR	260.00	-
1	GEAR ROD	BENT	105.00	105.00
1	GEAR PEDAL	BENT	75.00	75.00
1	FRONT LH FOOTREST	BENT / CUT	85.00	85.00
1	FRONT LH FOOTREST BRACKET	BENT	155.00	155.00
1	ENGINE BRACKET	BROKEN	135.00	135.00
1	REAR TAIL PANEL	TO REPAIR SEE LABOUR	165.00	-
1	REAR PILLION FOOTREST BRACKET LH	BENT	155.00	155.00
1	PILLION FOOTREST	BENT	95.00	95.00
1	REAR MUDGUARD	NOT NECESSARY	195.00	-

Report Ref No. CC4/FCI20002023/Dda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL AXLE-FRONT	DISTORTED	125.00	125.00
2	LOWER ENGINE COVER	BROKEN	270.00	270.00
1	FRONT BRAKE CALIPER	NOT NECESSARY	135.00	-
1	RADIATOR ASSY	PUNCTURE	550.00	550.00
1	FORK STABILIZER BRACKET	BENT	250.00	250.00
1	SET FORK OIL SEAL	NECESSARY	125.00	125.00
2	LEG SHIELD -LH/RH	CUT	270.00	270.00
2	SIDE FAIRING INNER PANEL	BROKEN	240.00	240.00
1	RADIATOR GUARD	BENT	220.00	220.00
1	FRONT MUDGUARD BRACKET	BENT	210.00	210.00
1	RADIATOR FAN COWLING	BROKEN	180.00	180.00
	LESS 10% DISCOUNT		-824.30	-674.25
			7,418.70	6,068.25
	LABOUR			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NEW PARTS ,ALIGN & ETC .INCLUSIVE OF THE REPAIR OF PETROL TANK AND REAR TAIL PANEL.		350.00	200.00
	REMOVE & REPLACE FORK ASSY ,OIL SEAL & TOP UP FORK OIL.		90.00	80.00
	REMOVE & REPLACE FRONT RIM ,BRAKE DISC ,BRAKE CALIPER.		150.00	30.00
	PUTTY & RESPRAY PAINT & FRONT RIM .		450.00	150.00
	CHECK ELECTRICAL WIRING & CONNECTIONS.		60.00	30.00
			1,140.00	490.00
	GRAND TOTAL		8,558.70	6,558.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CC4/FCI20002023/Dda3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.