



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005327  
INV Date 30/07/2020  
Reference CC4/FCI20002028/Gka3s2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. FBN 4845E  
Insured Veh. SHC 8637A  
Claim No. D19006028MFSH  
Policy No. D-19092580MFSH  
Accident Date 16/09/2019  
Inspection Date 05/02/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20002028/Gka3s2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 30-07-2020
	Code : FCI2



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SHC 8637A	<b>Veh. Inspected</b>	FBN 4845E
<b>Policy No.</b>	D-19092580MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D19006028MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOANNE YONG	<b>Assign Date</b>	05/02/2020

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA CBF190WH	<b>c.c</b>	184
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	LWBMC4695J1307803	<b>Colour</b>	ORANGE
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	110/70 R17	CST	5 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	140/70 R17	CST	5 mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.
--	---

**5. General Information**

<b>Accident Date</b>	16/09/2019	<b>Inspection Date</b>	05/02/2020
<b>Survey held at</b>	BOON SIEW SINGAPORE PTE LTD 370 UBI ROAD 3 SINGAPORE 408651		

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

**5b. Estimate Days of Repair**

	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
--	-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 4845E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BAR COMP, SIDE STAND (SN)	BENT	11.50	11.50
1	MIRROR COMP, R (SN)	CUT	24.60	24.60
1	MIRROR COMP, L (SN)	CUT	24.60	24.60
1	LEVER COMP, R HNDL (SN)	NOT NECESSARY	14.50	-
1	SET ILLUSTR, R STROUD (SN)	CUT	196.00	196.00
1	SET ILLUSTR, L SHROUD (SN)	CUT	162.50	162.50
1	PEDAL, RR. BRAKE (SN)	BENT	23.90	23.90
1	CHANGE RUBBER PEDAL (SN)	CUT	5.50	5.50
1	PEDAL COMP, CHANGE (SN)	BENT	29.90	29.90
1	RUBBER, MAIN STEP (SN)	MISSING	6.50	6.50
1	PLATE, STEP SET (SN)	MISSING	2.50	2.50
1	ARM, R, MAIN STEP (SN)	BROKEN	17.00	17.00
2	COLLAR 6MM (SN)	NECESSARY	3.00	3.00
2	BOLT, HEX. CAP 6X1 (SN)	NECESSARY	3.60	3.60
1	BLT SPECIAL 5X14 (SN)	NECESSARY	2.35	2.35
1	AEM, R. PILLION STEP (SN)	CUT	18.00	18.00
1	HOLDER, R. PILLION STEP (SN)	CUT	50.80	50.80
1	MUFFLER COMP, EXH (SN)	CUT	377.00	377.00
1	COVER A, MUFFLER (SN)	CUT	11.70	11.70
1	COVER B, MUFFLER (SN)	CRACKED	31.50	31.50
1	FENDER ASSY, FR (SN)	CUT	78.60	78.60
1	COWL SET, R. RR. (WL) (SN)	CUT	43.50	43.50
1	COWL SET, L. RR (WL) (SN)	CUT	43.50	43.50
1	DAMPER COMP, R FRONT (SN)	CUT	314.70	314.70
1	PIPE COMP, R. STEERING HANDLE *NH303M* (SN)	BENT	171.80	171.80
2	WEIGHT, STEERING HANDLE (SN)	CUT	9.61	9.60
1	CABLE COMP A, THROT (SN) (ADDITIONAL)	CUT	17.00	17.00
1	CABLE COMP B, THROT (SN) (ADDITIONAL)	CUT	16.50	16.50
1	WINKER ASSY, RFR (SN) (ADDITIONAL)	CUT	122.80	122.80
1	HOLDER. R. MAIN (SN) (ADDITIONAL)	CUT	85.49	85.49



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LEVER COP, L HNDL (SN) (ADDITIONAL)	CUT	22.50	22.50
			1,942.95	1,928.44
	<b>LABOUR</b>			
	TOWING FROM TRAFFIC POLICE TO BSS.		35.00	35.00
	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT.		1,120.00	840.00
	USING MCS TO ERASE / RESET DTC CODE.		120.00	120.00
	KAPPA K42 TOP BOX.		92.30	92.30
			1,367.30	1,087.30
<b>GRAND TOTAL</b>			<b>3,310.25</b>	<b>3,015.74</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,015.74</b>

Report Ref No. CC4/FCI20002028/Gka3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 4845E

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 4845E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBN 4845E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

