

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20002031/GKS3Q2

**Date:** 03/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900168965

**Claimant**  
**Vehicle No :** SJV909U **Insured Vehicle No :** SMP5095E

Date of Loss: 03/02/2020 Nature of Claim: TP Claim No: 6788969448SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJV909U</b>		
Make & Model:	BMW X1, 2.0 SDRIVE20I (A)	Engine No:	F2091550B48A20A
Reg. Date:	25/11/2016 (Man. Year: 2016)	Chassis No:	WBAHS720405G65750
Colour:	White	Odometer:	37761 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,689.65	1,689.65	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,356.65</b>	<b>3,773.65</b>	<b>583.00</b>	<b>13.38</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	304.97	264.16	40.81	13.38
<b>Nett Amount (\$\$)</b>	<b>4,661.62</b>	<b>4,037.81</b>	<b>623.81</b>	<b>13.38</b>
<b>+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (\$\$)</b>		385.20		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,425.01</b>		

### INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Cut	854.55 FS	*854.55 FS
3	1		*RH OPEN GRID (SPORT LINE PDC)	Cut	106.35 FS	*106.35 FS
4	1		*FRT BUMPER PANEL LOWER SECTION (PDC)	Cut	213.65 FS	*213.65 FS
5	1		*FRT RH WHEEL ARCH TRIM	Cut	151.80 FS	*151.80 FS
6	1		*RH FOGLAMP	Cracked	283.30 FS	*283.30 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **1,689.65**      **1,689.65**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE BUMPER FRONT COVER AND ATTACHMENTS	New	1,275.00	850.00
2	TO SPRAY PAINT BUMPER FRONT COVER	New	1,038.00	934.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,667.00</b>	<b>2,084.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**