



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102566

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/04/2021
Reference CC4/FCI20002033/Apa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 965Y
Insured Veh. SHC 992B
Claim No. D20000763MFSH
Policy No. D-20094921MFSH
Accident Date 31/01/2020
Inspection Date 05/02/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20002033/Apa3q2	
			Date: 14/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 992B	Veh. Inspected	SLE 965Y	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20000763MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	04/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104554426	Colour	SILVER	
Odometer	226509 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HABILEAD	6 mm	
L/H Front Tyre	205/55 R16	HABILEAD	6 mm	
R/H Rear Tyre	205/55 R16	HABILEAD	6 mm	
L/H Rear Tyre	205/55 R16	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGEE SEE DETAILS.				
5. General Information				
Accident Date	31/01/2020	Inspection Date	05/02/2020	
Survey held at	2 KAKI BUKIT AVE 2 #01-18 SINGAPORE 417921			
Repairer	N-51 AUTOMOTIVE PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 965Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIRCON CONDENSER	DENTED	1,289.00	1,289.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,140.40	-
2	FRONT BONNET HINGES L/R @ \$135.10	NOT NECESSARY	270.20	-
1	FRONT BONNET MECHANISM LOCK	DAMAGED	271.85	135.00
1	FRONT BONNET TOP RUBBER MOULDING	NOT NECESSARY	40.00	-
1	FRONT BRACE PANEL	BENT	182.10	182.10
1	FRONT BUMPER	DEFORMED	581.45	581.45
1	FRONT BUMPER LOWER GRILLE	DEFORMED	191.40	191.40
1	FRONT BUMPER REINFORCEMENT	BENT	374.45	374.45
2	FRONT BUMPER SIDE RETAINER L/R @ \$132.10	NECESSARY	264.20	264.20
1	FRONT BUMPER SPONGE	CRACKED	186.10	186.10
1	FRONT GRILLE	CRACKED	595.90	595.90
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	65.45	65.45
1	FRONT GRILLE TOP GARNISH	DEFORMED	92.00	92.00
1	FRONT GRILLE TOP RUBBER MOULDING	NOT NECESSARY	181.90	-
2	FRONT HEADLAMP L/R @ \$850.00	CRACKED	1,700.00	1,700.00
2	FRONT HEADLAMP LOWER BRACKET L/R @ \$132.10	NOT NECESSARY	264.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	2,121.40	-
1	RADIATOR TOP BRACKET	CRACKED	174.40	174.40
2	REAR BOOTLID REFLECTOR L/R @ \$374.45	NOT NECESSARY	748.90	-
1	REAR BOOTLID	BUCKLED	781.10	781.10
1	REAR BOOTLID 'ALTIS' EMBLEM	NECESSARY	54.10	54.10
1	REAR BOOTLID 'COROLLA' EMBLEM	NECESSARY	50.20	50.20
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	58.50	58.50
2	REAR BOOTLID HINGES L/R @ \$79.60	NOT NECESSARY	159.20	-
2	REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R @ \$17.00	NOT NECESSARY	34.00	-
1	REAR BOOTLID INNER TRIM BOARD	NOT NECESSARY	181.85	-
1	REAR BOOTLID LOCK STRIKER	NOT NECESSARY	85.00	-
1	REAR BOOTLID MECHANISM LOCK	DAMAGED	379.20	379.20

Report Ref No. CC4/FCI20002033/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOTLID WEATHER STRIP	CUT	271.45	271.45
1	REAR BUMPER	DEFORMED	581.90	581.90
2	REAR BUMPER REFLECTOR L/R @ \$141.45	CRACKED	282.90	282.90
1	REAR BUMPER REINFORCEMENT	BENT	398.70	398.70
2	REAR BUMPER REINFORCEMENT BRACKET L/R @ \$165.00	DENTED	330.00	330.00
2	REAR BUMPER REVERSE SENSOR @ \$265.30	DAMAGED	530.60	530.60
2	REAR BUMPER REVERSE SENSOR HOLDER @ \$121.10	NOT NECESSARY	242.20	-
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	715.20	-
2	REAR BUMPER SIDE RETAINER L/R @ \$65.00	NECESSARY	130.00	130.00
1	REAR END PANEL	DENTED	781.90	781.90
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	185.99	185.99
1	REAR EXHAUST GASKET	NOT NECESSARY	63.20	-
2	REAR EXHAUST RUBBER MOUNTING @ \$63.90	NOT NECESSARY	127.80	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	1,255.00	-
2	REAR FENDER INNER TRIM L/R @ \$338.00	N/S TORN	676.00	338.00
1	REAR FLOOR PANEL TOP BOARD COVER	DEFORMED	485.10	485.10
2	REAR TAILLAMP INNER BACK RUBBER GASKET L/R @ \$25.50	NECESSARY	51.00	51.00
2	REAR TAILLAMP L/R @ \$391.90	CUT	783.80	783.80
2	REAR TAILLAMP LOWER BRACKET L/R @ \$88.70	CRACKED	177.40	177.40
	LESS 25% DISCOUNT		-5,147.15	-3,120.82
			15,441.44	9,362.47
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
1	SET REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
2	SET REAR FENDER INNER TRIM CLIPS L/R @ \$50.00 (SN)	NECESSARY	100.00	30.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-

Report Ref No. CC4/FCI20002033/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR TAILLAMP CLIPS L/R @ \$20.00 (SN)	NECESSARY	40.00	40.00
			795.00	215.00
	LABOUR			
	TO REMOVE, CHARGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.		120.00	60.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. TO (TO FR)		80.00	30.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,400.00	800.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.		1,200.00	600.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	100.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT SUPPORT PANEL.		2,400.00	1,400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR.		80.00	60.00
			5,740.00	3,150.00
GRAND TOTAL			21,976.44	12,727.47



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,100.00
---	--	--	-----------

Report Ref No. CC4/FCI20002033/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 965Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 965Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 965Y

RE-INSPECTION

