

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002035/UHS3Q2

Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100291651

Claimant
Vehicle No : SKJ1561H **Insured Vehicle No :** SKK4040U

Date of Loss: 08/01/2020 Nature of Claim: TP Claim No: 1151514308SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SKJ1561H | | |
| Make & Model: | MERCEDES-BENZ C180, 1.8 Blue Efficiency (A) | Engine No: | 27491030028528 |
| Reg. Date: | 26/02/2013 (Man. Year: 2012) | Chassis No: | WDD2040312A801644 |
| Colour: | Blue | Odometer: | 112280 km |
| Engine Capacity: | 1595 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/55Z R17 | Rear Tyre Size: | 225/55Z R17 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,022.30 | 1,112.40 | 909.90 | 44.99 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,720.00 | 900.00 | 820.00 | 47.67 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,742.30 | 2,012.40 | 1,729.90 | 46.23 |
| Approved Total (Overridden) (S\$) | | 1,600.00 | | |
| (S\$) | 3,742.30 | 1,600.00 | 2,142.30 | 57.25 |
| + GST 7.00/7.00% (S\$) | 261.96 | 112.00 | 149.96 | 57.25 |
| Nett Amount (S\$) | 4,004.26 | 1,712.00 | 2,292.26 | 57.25 |
| + Loss of Use (2.0 x S\$60.00/day) (S\$) | | 120.00 | | |
| + Car Rental (2.0 x S\$100.00/day) (S\$) | | 200.00 | | |
| + Doc/Search Fee (S\$) | | 8.00 | | |
| Nett Liability (S\$) | | 2,040.00 | | |
| Global Sum Settlement (S\$) | | 2,000.00 | | |

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|--------------------------------|-------------|--------------|
| 1 | 1 | | *TAIL LAMP LH (Cracked) | Not Consistent With The Impact | 605.00 FL | *- FL |
| 2 | 1 | | *SIDE MIRROR LH | Grazed / Damaged | 1,150.00 FL | *1,150.00 FL |
| 3 | 1 | | *SIDE MIRROR COVER WITH SIGNAL LIGHT | Serviceable | 406.00 FL | *- FL |
| 4 | 1 | | *REAR DOOR CHROME MOULDING LH | Necessary | 86.00 FL | *86.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 2,247.00 | 1,236.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 224.70 | 123.60 |
| Total Parts (\$) | 2,022.30 | 1,112.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO RESPRAY AFFECTED AREAS(REAR BUMPER ,REAR LH FEMDER ,REAR LH DOOR,LH SIDE MIRROR & REAR SPORT RIM) | New | 1,200.00 | 600.00 |
| 2 | TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS | New | 400.00 | 300.00 |
| 3 | TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT | New | 120.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,720.00 | 900.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >