



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 6926X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LHS REAR DOOR (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	LHS REAR DOOR PROTECTOR (CONSISTENT)	NECESSARY	232.00	232.00
1	LHS REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	982.00	-
1	LHS REAR FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	238.00	-
1	LHS REAR TAILLAMP (CONSISTENT)	NOT NECESSARY	745.00	-
1	REAR BUMPER (CONSISTENT)	CUT	1,120.00	485.10
2	REAR BUMPER RETAINER (LONG) @\$75.00 (CONSISTENT)	NOT NECESSARY	150.00	-
2	REAR BUMPER RETAINER (SHORT) @\$68.00 (CONSISTENT)	NOT NECESSARY	136.00	-
2	REAR BUMPER REFLECTORS @\$72.00 (CONSISTENT)	NOT NECESSARY	144.00	-
1	LHS SIDE SKIRTING (CONSISTENT)	CUT / TORN	780.00	780.00
1	LHS REAR SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	592.00	-
1	LHS REAR WHEEL BEARING (CONSISTENT)	DAMAGED	248.00	248.00
	LESS 25% DISCOUNT		-1,341.75	-436.28
			4,025.25	1,308.82
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR LHS FENDER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR LHS SPORT RIM (SN) (CONSISTENT)	CUT / BENT	980.00	400.00
1	LHS REAR FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN INNER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			1,300.00	440.00
<b><u>LABOUR</u></b>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF LHS REAR DOOR AND LHS REAR FENDER.		1,400.00	520.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED LHS REAR DOOR.	NOT NECESSARY	900.00	800.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		140.00	-
	TO REMOVE AND REPLACE LHS REAR UNDERCARRIAGE PARTS (SUSPENSION SYSTEM).		250.00	120.00
	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST .		120.00	80.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		180.00	80.00
			2,990.00	1,600.00
<b>GRAND TOTAL</b>			<b>8,315.25</b>	<b>3,348.82</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,650.00</b>
---	--	--	--	-----------------

Report Ref No. CC4/ASM20002036/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.