

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/FWD20002040/KGS3Q2  
**Date:** 26/06/2020REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00005929
<b>Claimant</b>			
<b>Vehicle No :</b>	SML2443A	<b>Insured Vehicle No :</b>	SJK3971B
Date of Loss:	02/02/2020	Nature of Claim:	TP
			Claim No: 1202000004799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML2443A</b>		
Make & Model:	AUDI A5, 2.0 TFSI QUATTRO (A)	Engine No:	CDN036562
Reg. Date:	11/06/2009 (Man. Year: 2009)	Chassis No:	WAUZZZ8T39A051755
Colour:	Red	Odometer:	157841 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,057.95	6,873.82	12,184.13	63.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	1,055.00	3,205.00	75.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,317.95</b>	<b>7,928.82</b>	<b>15,389.13</b>	<b>66.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,300.00</b>		
<b>(S\$)</b>	23,317.95	6,300.00	17,017.95	72.98
<b>+ GST 7.00/7.00% (S\$)</b>	1,632.26	441.00	1,191.26	72.98
<b>Nett Amount (S\$)</b>	<b>24,950.21</b>	<b>6,741.00</b>	<b>18,209.21</b>	<b>72.98</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>7,248.45</b>		

INSPECTION

Date of Assignment:	05/02/2020	
Date Inspected:	05/02/2020 Inspected At:	Leong Auto Pte Ltd (HQ) 160 Sin Ming Drive, #02-13, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 May 2020)	
<b>Parts:</b>	N/A	AUDI A5 2.0 TFSI QUATTRO (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML2443A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	2,236.30 FL	*- FL
2	1		*REAR BOOT LID LOCK MECHANISM	Repair	117.20 FL	*- FL
3	1		*REAR BOOT LID LOCK CATCH	Repair	97.20 FL	*- FL
4	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	178.70 FL	*- FL
5	1		*REAR END PANEL (OUTER)	Repair	850.00 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Serviceable	135.90 FL	*- FL
7	2		*REAR FENDER INNER TRIM	Serviceable	1,243.90 FL	*- FL
8	2		*TAIL LAMP	Serviceable	1,926.00 FL	*- FL
9	2		*TAIL LAMP SIDE RETAINER	Serviceable	83.50 FL	*- FL
10	2		*FENDER INNER SHIELD	Serviceable	299.60 FL	*- FL
11	1		*REAR BUMPER ASSY	Buckled	1,468.60 FL	*1,210.00 FL
12	1		*REAR BUMPER RETAINER	O/S Distorted	180.60 FL	*90.30 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	494.90 FL	*410.00 FL
14	2		*REAR BUMPER REINFORCEMENT BRACKET	Repair	452.20 FL	*- FL
15	1		*REAR BUMPER INNER GARNISH	Serviceable	264.30 FL	*- FL
16	1		*REAR BUMPER TOW COVER	Serviceable	148.50 FL	*- FL
17	1		*REAR BUMPER PARKING SENSOR (4 PCS)	Damaged (1 PCS ONLY)	959.80 FL	*239.95 FL
18	4		*REAR BUMPER PARKING SENSOR HOLDER	Necessary (1 PCS ONLY)	216.00 FL	*54.00 FL
19	1		*REAR BUMPER PARKING SENSOR WIRING	Serviceable	473.50 FL	*- FL
20	2		*REAR EXHAUST BRACKET	Repair	120.90 FL	*- FL
21	2		*REAR EXHAUST MOUNTING	Serviceable	127.90 FL	*- FL
22	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
23	1		*REAR BOOT LID LOGO	Not Necessary	180.00 FS	*- FS
24	1		*REAR END LOWER PANEL (INNER) SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR END TOP PANEL (INNER) SEALANT	Not Necessary	120.00 FS	*- FS
26	1		*REAR END PANEL (OUTER) SEALANT	Not Necessary	120.00 FS	*- FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
28	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
29	2		*REAR TAIL LAMP TINTING	Not Necessary	300.00 FS	*- FS
30	2		*SET TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
31	2		*SET FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR BUMPER ASSY CLIPS	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR BUMPER LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
34	1		*REAR BUMPER LOWER DIFFUSER LIP	Cracked	1,800.00 FS	*1,500.00 FS
35	1		*SET REAR BUMPER LOWER DIFFUSER LIP CLIPS	Necessary	80.00 FS	*80.00 FS
36	1		*REAR BUMPER LOWER DIFFUSER LIP SEALANT	Necessary	120.00 FS	*40.00 FS
37	1		*SET REAR EXHAUST ASSY	Bent	4,800.00 FS	*3,400.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
38	1		*SET REAR NO PLATE WITH GARNISH	Serviceable	80.00 FS	*-FS	
						F=Franchise part. S=SpcNett. L=ListItemDisc.	
					<b>Sub Total (\$)</b>	<b>20,265.50</b>	<b>7,074.25</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,207.55	200.43
					<b>Total Parts (\$)</b>	<b>19,057.95</b>	<b>6,873.82</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN AND REPLACE REAR DAMAGED PARTS	New	1,600.00	400.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	500.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	15.00
4	TO REMOVE AND INSTALL REAR BOOT LID LOCK MECHANISM	New	150.00	0.00
5	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	380.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	250.00	0.00
7	TO REMOVE AND INSTALL REAR PARKING SENSOR	New	150.00	60.00
8	TO CONDUCT COMPUTER DIAGNOSTIC TEST	New	180.00	0.00
9	TO REMOVE AND INSTALL EXHAUST MUFFLER AND REAR EXHAUST CENTRE PIPE	New	180.00	80.00
10	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID ,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	New	120.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,260.00</b>	<b>1,055.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >