

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20002041/KYF3E2

Date: 09/04/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29123167

Claimant Vehicle No : SLG6484T

Insured Vehicle No : SKN9706J

Date of Loss: 04/02/2020

Nature of Claim: TP Claim No: 619127

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG6484T

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRR916633

Reg. Date: 10/10/2016 (Man. Year: 2016)

Chassis No: JTDKB3FU503529084

Colour: Metallic Pearl White

Odometer: 254078 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 7 mm

Rear Left Side: West Lake 8 mm

Front Right Side: West Lake 7 mm

Rear Right Side: West Lake 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,967.59	1,800.69	7,166.90	79.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	715.00	825.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,507.59</b>	<b>2,515.69</b>	<b>7,991.90</b>	<b>76.06</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,000.00</b>		
<b>(\$\$)</b>	10,507.59	2,000.00	8,507.59	80.97
<b>+ GST 7.00/7.00% (\$\$)</b>	735.53	140.00	595.53	80.97
<b>Nett Amount (\$\$)</b>	<b>11,243.12</b>	<b>2,140.00</b>	<b>9,103.12</b>	<b>80.97</b>

### INSPECTION

Date of Assignment: 05/02/2020

Date Inspected: 06/02/2020 Inspected At:

E M Solution Pte Ltd (HQ)  
160 Sin Ming Drive,, #03-18, Sin Ming  
Autocity  
Singapore 575722

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2020)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG6484T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	677.90 FL	*677.90 FL
2	2		*REAR BUMPER SIDE RETAINERS	Serviceable	175.90 FL	*- FL
3	2		*REAR BUMPER BRACKETS	Repair	254.80 FL	*- FL
4	1		*REAR BUMPER LOWER DIFUSER	Bent	521.70 FL	*521.70 FL
5	2		*REAR BUMPER LAMPS	Serviceable	851.20 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	385.70 FL	*385.70 FL
7	2		*REAR BUMPER SENSORS	Dented	524.55 FS	*200.00 FS
8	1		*TAIL LAMPS ASSY	N/S Mtg Cracked/O/SServiceable	977.90 FL	*488.95 FL
9	1		*BOOT LID	Repair	1,221.70 FL	*- FL
10	1		*BOOT EMBLEM	Not Necessary	68.90 FL	*- FL
11	1		*BOOT PRIUS BADGE	Not Necessary	61.70 FL	*- FL
12	1		*BOOT HYBRID BADGE	Not Necessary	48.20 FL	*- FL
13	2		*BOOT NUMBER PLATE LAMPS	Serviceable	175.20 FL	*- FL
14	1		*BOOT RUBBER	Serviceable	323.90 FL	*- FL
15	1		*BOOT LOCK	Repair	381.60 FL	*- FL
16	1		*BOOT INNER LOCK	Serviceable	441.65 FL	*- FL
17	1		*REAR LOCK SENSOR	Serviceable	187.40 FL	*- FL
18	1		*REAR END PANEL	Repair	741.95 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Serviceable	221.60 FL	*- FL
20	1		*SPARE TYRE PANEL	Repair	821.95 FL	*- FL
21	1		*SPARE TYRE COVER	Serviceable	551.65 FL	*- FL
22	1		*REAR EXHAUST SILENCER	Repair	899.75 FL	*- FL
23	2		*REAR EXHAUST MOUNTINGS	Serviceable	94.40 FL	*- FL
24	1		*REAR WINDSCREEN MOULDING	Not Necessary	137.40 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*REAR NUMBER PLATE	Serviceable	70.00 FS	*- FS
29	1		*REAR CAMERA	Serviceable	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,523.60</b>	<b>2,319.25</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>2,556.01</b>	<b>518.56</b>
<b>Total Parts (\$)</b>	<b>8,967.59</b>	<b>1,800.69</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ELECTRICAL WIRINGS	New	60.00	15.00
2	REPAIR ACCIDENT DAMAGES AND RENEW PARTS	New	550.00	300.00
3	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	550.00	400.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
5	RENEW REAR CAMERA	New	100.00	0.00
6	RENEW REAR EXHAUST SILENCER	New	80.00	0.00
7	TUFF KOTE ON AFFECTED PORTIONS	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,540.00</b>	<b>715.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >