

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002045/KBS3Q2
Date: 28/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100360124
Claimant Vehicle No :	SCL361J	Insured Vehicle No :	SDJ228K
Date of Loss:	27/01/2020	Nature of Claim:	TP
		Claim No:	7999207712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCL361J	Engine No:	C03602
Make & Model:	PORSCHE PANAMERA, 3.6 PDK (A)	Chassis No:	WP0ZZZ97ZCL001596
Reg. Date:	28/12/2012 (Man. Year: 2011)	Odometer:	112131 km
Colour:	Metallic Black		
Engine Capacity:	3605 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/45Z R19	Rear Tyre Size:	285/40Z R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,219.50	21,239.37	6,980.13	24.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	2,050.00	860.00	29.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,129.50	23,289.37	7,840.13	25.19
Approved Total (Overridden) (S\$)		17,550.00		

Nett Amount (S\$)	31,129.50	17,550.00	13,579.50	43.62
+ Loss of Use (7.0 x S\$150.00/day) (S\$)		1,050.00		
Nett Liability (S\$)		18,600.00		

INSPECTION

Date of Assignment: 05/02/2020

Date Inspected: 05/02/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming Autocare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	2,158.00 FL	*2,158.00 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	78.00 FL	*78.00 FL
3	1		*LH HEADLAMP	Cracked	3,789.00 FL	*2,972.00 FL
4	1		*FRONT LH FENDER	Bent	1,975.00 FL	*1,875.00 FL
5	1		*FRONT LH SPORTS RIM	Dented	3,122.00 FL	*1,981.30 FL
6	1		*FRONT LH SHOCK ABSORBER	Bent	2,951.00 FL	*2,951.00 FL
7	1		*FRONT LH LOWER ARM	Necessary	1,877.00 FL	*1,877.00 FL
8	1		*FRONT LH KNUCKLE ARM	Bent	2,578.00 FL	*2,578.00 FL
9	1		*FRONT LH WHEEL HUB	Bent	971.00 FL	*971.00 FL
10	1		*FRONT LH WHEEL BEARING	Necessary	578.00 FL	*578.00 FL
11	1		*FRONT LH DOOR	Bent / Warped	3,895.00 FL	*3,895.00 FL
12	1		*FRONT LH DOOR WEATHERSTRIP	Serviceable	321.00 FL	*- FL
13	1		*REAR LH DOOR (LOCAL REPAIR)	Dented	3,892.50 FS	*450.00 FS
14	1		*REAR LH DOOR STICKER	Necessary	285.00 FL	*285.00 FL
15	1		*REAR LH DOOR WEATHERSTRIP	Serviceable	321.00 FL	*- FL
16	1		*LH ROCKER PANEL SPOILER	Serviceable	1,231.00 FL	*- FL
17	1		*LH HEADLAMP NOZZLE	Cracked	250.00 FL	*250.00 FL
18	1		*LH FRONT UPPER ARM	Bent	650.00 FL	*650.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,922.50	23,549.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,703.00	2,309.93
Total Parts (\$\$)	28,219.50	21,239.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	1,200.00	900.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,200.00	1,000.00
3	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE ,REFIT FRONT LH UNDER CARRIAGES	New	300.00	40.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
6	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	90.00	30.00
Gross Labour Cost (\$\$)			2,910.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >