



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 909E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,640.90	1,565.00
10	FRONT BUMPER CLIP @\$8.00 (CONSISTENT)	NECESSARY	80.00	30.00
2	FRONT BUMPER REVERSE SENSOR @\$368.80 (CONSISTENT)	DAMAGED (1 PC ONLY)	737.60	285.00
1	FRONT R/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	64.30	64.30
1	FRONT R/H BUMPER SIDE WASHER COVER (CONSISTENT)	NOT NECESSARY	81.90	-
1	FRONT R/H BUMPER SIDE WASHER NOZZLE MOTOR (CONSISTENT)	NOT NECESSARY	183.80	-
1	FRONT R/H BUMPER TOWING COVER (CONSISTENT)	NOT NECESSARY	62.00	-
1	FRONT R/H BUMPER FOG LAMP (CONSISTENT)	CRACKED	441.90	325.00
1	FRONT R/H BUMPER FOG LAMP COVER (CONSISTENT)	CRACKED	122.00	122.00
1	FRONT R/H BUMPER FOG LAMP TOP CHROME (CONSISTENT)	NOT NECESSARY	108.70	-
1	FRONT R/H HEADLAMP (CONSISTENT)	CRACKED	5,062.80	5,062.80
1	FRONT R/H HEADLAMP LOWER BRACKET(CONSISTENT)	NOT NECESSARY	131.60	-
1	FRONT R/H FENDER (CONSISTENT)	NOT NECESSARY	1,231.20	-
1	FRONT R/H FENDER COWLING (CONSISTENT)	DEFORMED	279.70	279.70
8	FRONT R/H FENDER COWLING CLIP @\$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	FRONT R/H FENDER STICKER (CONSISTENT)	NOT NECESSARY	300.00	-
1	FRONT R/H WHEEL RIM (CONSISTENT)	CUT	1,480.00	800.00
	LESS 10% DISCOUNT		-	-856.38
			12,060.40	7,707.42
<u>LABOUR</u>				
	TO REMOVE & REFIT CUSHION.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT FRONT BUMPER SENSOR.		180.00	60.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.		1,400.00	250.00

Report Ref No. CC4/ASM20002046/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,400.00	250.00
			3,610.00	590.00
GRAND TOTAL			15,670.40	8,297.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CC4/ASM20002046/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.