Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002047/T1ES3Q2

**Date:** 03/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant Vehicle No: SGU3783K Insured Vehicle No: SLR4186J

Date of Loss: 03/02/2020 Nature of Claim: TP Claim No: 1561783912SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SGU3783K

 Make & Model:
 HONDA CIVIC, 1.6 L VTI (A)
 Engine No:
 R16A12001101

 Reg. Date:
 14/05/2007 (Man. Year: 2007)
 Chassis No:
 JHMFD45207S200581

Colour: White Odometer: 0 km

Engine Capacity: 1595 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm
Front Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,266.54	1,656.32	3,610.22	68.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,410.00	1,070.00	43.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,746.54	3,066.32	4,680.22	60.42
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	7,746.54	2,450.00	5,296.54	68.37
+ GST 7.00/7.00% (S\$)	542.26	171.50	370.76	68.37
Nett Amount (S\$)	8,288.80	2,621.50	5,667.30	68.37
+ Car Rental (6.0 x S\$10	0.00/day) (S\$)	600.00		
+ Doc/Se	36.45			
Net	t Liability (S\$)	3,257.95		
Global Sum S	3,200.00			

**INSPECTION** 

Date of Assignment: 04/02/2020

Date Inspected: 05/02/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	733.70 FL	*733.70 FL
2	1	*REAR BUMPER RETAINER	N/S Not Necessary/O/SDeformed	32.90 FL	*16.45 FL
3	1	*REAR RH TAILLAMP	Cracked	550.15 FL	*452.00 FL
4	1	*REAR RH TAILLAMP PANEL	Repair	165.70 FL	*- FL
5	1	*REAR RH FENDER	Repair	919.72 FL	*-FL
6	1	*BOOTLID	Repair	710.00 FL	*- FL
7	2	*BOOTLID HINGE	Not Necessary	96.00 FL	*-FL
8	1	*BOOTLID WEATHERSTRIP	Not Necessary	195.00 FL	*-FL
9	1	*BOOTLID EMBLEM -HONDA	Not Necessary	45.00 FL	*-FL
10	1	*BOOTLID LAMP	O/S Cracked	466.50 FL	*233.25 FL
11	1	*END PANEL	Repair	631.00 FL	*-FL
12	1	*END PANEL TOP GARNISH	Deformed	160.00 FL	*160.00 FL
13	1	*REAR WINDSCREEN MOULDING	Not Necessary	40.00 FL	*- FL
14	1	*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
15	1	*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*-FS
16	1	*REAR BUMPER LOWER GARNISH	Deformed	800.00 FS	*350.00 FS
17	1	*JOINT SEALANT	Not Necessary	120.00 FS	*-FS
18	1	*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*-FS
F=Fra	nchise	part. S=SpcNett. L=ListItemDisc.		,	
			Sub Total (S\$)	•	1,975.40
- List Item Discount on L Items 20.00/20.00% (S\$)				949.13	319.08
			Total Parts (S\$)	5,266.54	1,656.32

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE, REFIT REAR LINING TRIM AND GARNISH	New	150.00	50.00
3	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	700.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
	Gross	Labour Cost (S\$)	2,480.00	1,410.00
	Report was unsubmitte	d during this print-out		

< END OF ESTIMATES >