

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002051/KEA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505983
Claimant
Vehicle No : SMP6244K **Insured Vehicle No :** SLM4009P
Date of Loss: 17/01/2020 Nature of Claim: TP Claim No: 1192226887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6244K**
Make & Model: HONDA STEPWAGON SPADA, 1.5 (A) Engine No: L15B5145522
Reg. Date: 03/10/2019 (Man. Year: 2019) Chassis No: RP31232237
Colour: Metallic Pearl White Odometer: 8054 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	840.00	260.00	23.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,100.00	840.00	260.00	23.64
+ GST 7.00/7.00% (S\$)	77.00	58.80	18.20	23.64
Nett Amount (S\$)	1,177.00	898.80	278.20	23.64
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,114.80		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 05/02/2020 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	500.00	400.00
2	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	440.00
Gross Labour Cost (\$\$)			1,100.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >