

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 17 Jul 2020

Preliminary Advice

Insured Vehicle No : SLP1987U
 TP Vehicle No : FBQ4364K Accident Date : 22/01/2020
 Make : LAMBRETTA 150 Assignment Date : 05/02/2020
 Date of Inspection : 15/07/2020 Est. Duration of Repair : 5
 Inspection At : A S PHOON PTE LTD (TOH GUAN) (HQ)
 BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35
 SINGAPORE 408701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,964.00
Revised Amount	:S\$	2,069.00
Check Items (Estimated)	:S\$	230.00
Total	:S\$	2,299.00
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.