

2203/2002

ASS. REC. BY:

REF: CS/ASM19022020/GtP3-1

Special Instruction:

Surveyor GR ASSIGNMENT (Office)

From (Person): Li Rui Hong of ASM (AXA) Date/Time: 5/2/2020

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLJ 361M Insured: PC 256Z

at Workshop m/s Complex VMS Tel: 6455 0012

of B1C 176 Sun Ming Drive #03-14

Policy No: \_\_\_\_\_ Claim No: S9M02A32

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 12. Dec. 2019

CA / REV / REP. / REV 24 HRS map 16.12.2019

Date/Time: 13.12.19 5.04pm Person Contacted: Li Hui H.O.D. Endorsement: \_\_\_\_\_

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 361M - x
	PC 256Z - CS5 ASSIGNMENT / G. P. 11/1/2019
20/12-	revised PRS via Smart claims
	Submit PRS Report
	Dismantle parts : 18.12.2019
	\$15100, 10 Days.

# VEHICLE INSPECTION REPORT

To : Mr. Jimmy Kok Pak Keen  
c/o 176 Sin Ming Drive  
#03-14 Sin Ming Autocare  
Singapore 575721

Our Ref. : PT1912005-L  
Policy No. :  
Claim No. :  
Sum Insured :  
Excess : T/P Claim  
Date : 04th January 2020

Assigned By : Mr. Jimmy Kok Pak Keen  
Date of Assignment : 16th Dec 2019  
Date of Accident : 12th Dec 2019  
Date of Inspection : 16th Dec 2019 Follow up inspections were also conducted.  
Name of Workshop : Complete VMS Pte Ltd  
Place of Inspection : 176 Sin Ming Drive #03-14 Sin Ming Autocare  
Singapore 575721

## PARTICULARS OF VEHICLE

Registration No.	: SLJ 0361 M	Odometer/km	: 67781
Make/Model	: Nissan Qashqai 2.0	Chassis No.	: SJNFBAJ11U1770834
Type Of Body	: SUV	Engine No.	: MR20429928W
Year of Manuf./Regn.	: 2016	Engine Cap.	: 1997 cc
Colour	: Black	Carrying Cap.	: 4 Passengers

## PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good	Market Value	: N/A
Footbrake	: Serviceable	Paint Work	: Good	Scrap Value	: -
Steering	: Serviceable	Modifications	: None	Others	: -

## CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread	: 225/45 - R19	6mm - Dunlop	6mm - Dunlop
Rear Tread (inner)	:		
Rear Tread (outer)	: 225/45 - R19	6mm - Dunlop X	6mm - Dunlop

*The above represent an estimated remaining life of the tyre treads in mm.*

## POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained impacts on the front and rear portions.

**FRONT** :- The bonnet, radiator support panel, front bumper, bumper reinforcement, oil cooler unit, aircond condenser, n/s front fender, fender inner panel were dented/ buckled/ distorted.

**REAR** :- The rear chassis members, tail gate, boot floor cum spare wheel well panel, boot floor extension panels, rear end panel, tail lamp trough panels, rear bumper, bumper reinforcement, exhaust heat shield were badly dented/ buckled/ distorted.

For details of damages please refer to our schedule attached.

## REMARKS :

This survey was conducted strictly without prejudice.

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore*

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
NETT ITEMS:				
1	radiator grille	chafed/grazed	S\$ 558.30	S\$ / 558.30
1	radiator grille chrome garnish	chafed/grazed	322.00	SVC X 322.00
1	n/s head lamp	snapped	1,617.00	/ 1,617.00
1	o/s head lamp	snapped	1,617.00	/ 1,617.00
1	front bumper	dented/distorted	681.60	/ 681.60
6	front bumper clips	necessary	38.40	/ 38.40
2	front bumper bracket	damaged	295.40	SVC X 295.40
1	front bumper n/s retainer	damaged	32.90	X 32.90
1	front bumper reinforcement	dented/distorted	715.40	685 / 715.40
1	front bumper reinforcement n/s brkt	damaged	153.00	/ 153.00
1	front bumper inner sponge	damaged	225.70	/ 225.70
1	front bumper tow cover	damaged	32.90	/ 32.90
1	front n/s fog lamp garnish	snapped	94.70	SVC X 94.70
1	aircon condenser n/s side cover	damaged	263.00	145 / 263.00
1	tail gate	badly dented	2,936.80	/ 2,936.80
1	tail gate glass c/w moulding	damaged	960.00	195.3 / 960.00
2	tail gate shock absorber	serviceable	459.60	-
1	tail gate lock	bent/stiffened	176.70	/ 176.70
1	tail gate weatherstrip	damaged	158.70	/ 158.70
1	tail gate inner trimboard	warped	366.50	SVC X 366.50
1	tail gate number plate garnish	damaged	336.00	/ 336.00
2	tail gate number plate lamp	damaged	74.40	SVC X 74.40
1	tail gate lower chrome garnish	dented/distorted	366.00	166 / 366.00
1	tail gate logo	damaged	59.70	38.5 / 59.70
1	tail gate emblem - QASHQAI	damaged	87.00	78.5 / 87.00
1	tail gate o/s reflector	broken	265.90	/ 265.90
1	tail gate n/s reflector	chafed/cracked	265.90	/ 265.90
1	o/s tail lamp	broken	323.70	/ 323.70
1	n/s tail lamp	cracked	323.70	SVC X 323.70
1	rear bumper	badly dented	717.00	/ 717.00
6	rear bumper clips	necessary	38.40	/ 38.40
2	rear bumper bracket	damaged	312.00	SVC X 312.00
2	rear bumper side retainer	damaged	131.80	50 / 131.80
1	rear bumper reinforcement	badly dented	619.20	/ 619.20
2	rear bumper reinforcement brkt	damaged	370.00	/ 370.00
1	rear bumper inner sponge	damaged	156.40	SVC X 156.40
1	rear bumper tow cover	damaged	26.80	16.8 / 26.80
1	rear bumper reflector	snapped	130.00	68 / 130.00
1	rear end panel	badly dented	482.60	/ 482.60
1	rear end panel top garnish	damaged	163.50	/ 163.50
1	spare-tyre well panel	badly buckled	1,680.00	1182.3 / 1,680.00
1	spare-tyre top board	damaged	494.70	SVC X 494.70
1	rear speaker board	serviceable	458.30	-
1	n/s rear wheel arch garnish	damaged	483.00	/ 483.00
1	o/s rear wheel arch garnish	damaged	483.00	/ 483.00
1	exhaust top heat shield	buckled	166.80	/ 166.80
1	driver's seat belt holder	damaged	170.40	/ 170.40
			S\$ 20,891.80	S\$ 19,973.90
			LESS 10%	10% 1,997.39
			<u>S\$ 18,802.62</u>	<u>S\$ 17,976.51</u>

15686.9  
10%: 14118.21

Balance c/d S\$ 18,802.62 S\$ 17,976.51

# PREMIER APPRAISER SERVICES

12005-L

Vehicle No : SLJ 0361 M

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
		Balance b/f	S\$ 18,802.62	S\$ 17,976.51
	<b>S/NETT ITEMS:</b>			
1	front bumper sensor	damaged	360.00	SVC X 280.00
1	front number plate	dented	25.00	40 50.00
1	front number plate holder	dented	33.00	40 50.00
1	oil cooler	dented/punctured	604.20	405 - 604.20
1	aircon condenser	dented/bent	758.20	589.5 / 758.20
1	tail gate glass sealant	necessary	65.00	40 60.00
1	rear wiper motor	damaged	461.70	SVC X 461.70
1	rear number plate	dented	25.00	40 50.00
1	rear number plate holder	dented	33.00	40 50.00
1	reverse camera	damaged	850.00	SVC X 650.00
1	reverse sensor	damaged	380.00	200 250.00
		<b>TOTAL S/PARTS</b>	<b>S\$ 22,397.72</b>	<b>S\$ 21,140.61</b>
	To remove aircon condenser, vacuum & recharge gas.		280.00	/ 120.00
	To remove/replace tail gate glass.		180.00	/ 120.00
	To remove/refit luggage trims & garnish to assist repairs.		180.00	80 120.00
	To transfer tail gate fittings.		180.00	60 80.00
	Labour charges to repair, panel beat and straighten damaged parts and replace the above <b>front</b> body parts.		950.00	400 700.00
	Labour charges to repair, panel beat and straighten damaged parts and replace the above <b>rear</b> body parts. -		1,800.00	1200 1,400.00
	To repair exhaust silencer & replace heat shield.		100.00	60 80.00
	To replace front parking sensor & reverse sensor.		180.00	40 100.00
	To replace reverse camera.		180.00	40 80.00
	To check wiring functions.		100.00	30 50.00
	To putty, apply primer & spray-paint the affected areas.		1,600.00	1200 1,500.00
	To apply rust proofing on repaired/replaced panels.		180.00	390 80 160.00
		<b>TOTAL</b>	<b>S\$ <u>28,307.72</u></b>	<b>S\$ <u>25,650.61</u></b>

18862.71  
200%: 15100

10 Days.

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 21,800.00 lump sum** corresponding to supply of parts, labour and spray painting charges.

The estimated period of repairs is **FOURTEEN ( 14 )** days. Pursuant to your instruction we have **not** authorised repairs on your behalf.

## PREMIER APPRAISER SERVICES

**LESLIE K C LIM CAE (UK), MIMI (UK)**  
**MSAAA, Automotive Appraiser**  
**Dip.MTM. Automotive Engineer**