

ASS. REC. BY:

REF: CS / MSG 20002063 / D1 f30

Special Instruction:

Survivor: Bryan

ASSIGNMENT (Office)

From (Person): Crystal Lee

of MSG

Date/Time: 6-2-2020 10:26 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 9637L

Insured: SL L 1785G

at Workshop m/s Bigfrost Auto

Tel: 96212187

of Blk 9 Sector C #01-42

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.1.2020

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 6/2/20 10:47 a.m

Person Contacted: ms Lim

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 9637L - (C4 / AXA 17015 405 / Klub 352 D.O.A - 08/08/2017
	SL L 1785G - X
11/2/20	Send preli revised via merimen

ASS. REC. BY:

REF:

ASSIGNMENT

COE Aug 2026

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs 119 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SH 9637L Yr Regn: 2018, Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry  Taxi Prime Mover /

Truck / Trailer or 1580

Make: Hyundai Ioniq c.c. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 225482 T/Radio: Insured / Std / NI / NA

Eng/No: G4LEJU076120

C/No: KMHC851CVK-U106502

Gen. Cond: 6 Good / Fair / Poor / Burnt

Steering: 6 In order / Jammed / Leaked / Burnt or

Brake: 6 In order / Jammed / Leaked / Burnt or

Modi: 6 Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Duraturon

Front 5 mm Rear 5 mm

R/Bal. 5 mm L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 29/01/2020 D.O.I. 06/02/2020

Survey held at Biggest Sun Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Bent y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSIG SLL1785G

20/03/2020 Invoice 2/S 13900/- with 11 days of inv (Red \$17120-52,55%)

RECEIVED 23 MAR 2020

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 23/3/20 Typist

Days Of Repair: 11

Resurvey No. of Trip: 3

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Table with Survey Fee: 290, Transportation: S + RS \$1, Photos: 11, TOTAL: 261

Permit Format: Temp. Sum. R.P.J. CH \$13900/-

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Jowyn Tay Mei Ling	
<b>Date:</b> 11 Feb 2020	
<h3><u>Preliminary Advice</u></h3>	

<b>Insured Vehicle No :</b> SLL1785G	
<b>TP Vehicle No :</b> SH9637L	<b>Accident Date :</b> 29/01/2020
<b>Make :</b> HYUNDAI AE IONIQ HEV DCT	<b>Assignment Date :</b> 06/02/2020
<b>Date of Inspection :</b> 06/02/2020	<b>Est. Duration of Repair :</b> 9.00
<b>Inspection At :</b> BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644	

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,410.76
Revised Amount	:S\$	18,532.64
Check Items (Estimated)	:S\$	0.00
<b>Total</b>	<b>:S\$</b>	<b>18,532.64</b>

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Thursday, 6 February 2020 10:36 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** SH 9637L - GIA Report.pdf

### PRS For our client's vehicle SH9637L and your insured's vehicle SLL1785G (Grab) on 29.01.2020.

#### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

**Crystal Lee**

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua <helene\_phua@sg.msig-asia.com>

**Sent:** Thursday, 6 February 2020 10:27 AM

**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>

**Subject:** FW: Re : PRS For our client's vehicle SH9637L and your insured's vehicle SLL1785G (Grab) on 29.01.2020.  
Inbox x

*Have a great week ahead!*

**Helene Phua**

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua  
**Sent:** Thursday, 6 February 2020 10:27 AM  
**To:** Claims Dept <[claims\\_ltm@bifrostauto.com](mailto:claims_ltm@bifrostauto.com)>  
**Cc:** Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)>  
**Subject:** RE: Re : PRS For our client's vehicle SH9637L and your insured's vehicle SLL1785G (Grab) on 29.01.2020.  
Inbox x

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

*Have a great week ahead!*

**Helene Phua**  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Claims Dept <[claims\\_ltm@bifrostauto.com](mailto:claims_ltm@bifrostauto.com)>  
**Sent:** Wednesday, 5 February 2020 5:15 PM  
**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>  
**Cc:** Assessment <[claims@bifrostauto.com](mailto:claims@bifrostauto.com)>; Claims Dept <[claims\\_ltv@bifrostauto.com](mailto:claims_ltv@bifrostauto.com)>; [claims\\_ltr@bifrostauto.com](mailto:claims_ltr@bifrostauto.com); Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>  
**Subject:** RE: Re : PRS For our client's vehicle SH9637L and your insured's vehicle SLL1785G (Grab) on 29.01.2020.  
Inbox x

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

WITHOUT PREJUDICE

Hi,

We selected LKK.

Pls assign them asap.

Thanks & Regards,  
Bifrost Auto Pte Ltd  
Accident Claims Dept

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/01/2020 15:53
Date Of Accident	29/01/2020 23:30
Exact Location Of Accident	AIRPORT BLVD >> PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9637L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXXX21R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	ONG LIN HUAT
NRIC No	SXXXX169Z
Date Of Birth	12/11/1955
Occupation	OUTDOOR
Date Of Driving Pass	31/10/1975
Driving Experience	44 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86860679
Fax Number	
Contact Number	
EEmail Address	JOHNNIEONG@YMAIL.COM

Address	11 01-02 ANG MO KIO AVENUE 9
Postcode	569763
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: ; - GENDER: ; MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BISHAN NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT NO: T/20200130/2054

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL1785G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BRANDON TAN
NRIC/Passport Number	
Contact Number	96736555
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	ONG LIN HUAT
Approximate Age	65
Injuries Sustain	BACK
Injured person in which vehicle?	SH9637L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)

Date & Time: 30.01.2020  
@ 15:00 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

A - SH 9637L  
B - SLL 1785G  
C - SHB 5470M



Along Airport BLVD TWDS PIE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20200130/2054

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 30.01.2020  
@ 15:00 hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20200130/2054

1 of 4

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20200130/2054

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 30/01/2020 12:59	Vide Report No.:	Station Diary No.: 65
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: ONG LIN HUAT		Address: BLK 11 ANG MO KIO AVENUE 9 #01-02 SINGAPORE 569763	
ID Type / ID No.: NRIC NO / S1211169Z		Contact No.: Home/Office:                      Mobile: 86860679	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 64	Date of Birth: 12/11/1955	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3,4	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/01/2020 23:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 AIRPORT BOULEVARD PAN ISLAND EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SH9637L	Car	HYUNDAI	AE IONIQ HEV 1.6 DCT	Blue	Seriously Damaged	1
SHB5470M	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Maroon		0
SLL1785G	Car	MAZDA	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT	Black		0



**SINGAPORE  
POLICE FORCE**



T/20200130/2054

2 of 4

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20200130/2054

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ONG LIN HUAT	ID No.	S1211169Z
Related Vehicle	SH9637L (Car)	Contact No.	86860679
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	30/01/2020	Date Discharge	30/01/2020
No. of Days granted Medical Leave	04	Degree of Injury	Slight
<b>Driver</b>			
Name	LEE SIAN PIN	ID No.	S2131694F
Related Vehicle	SHB5470M (Car)	Contact No.	98389356
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	BRANDON TAN	ID No.	S9505015H
Related Vehicle	SLL1785G (Car)	Contact No.	96736555
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 29/1/2020 at about 2330hrs, I was driving my car - SH9637L along lane 1 of Airport Boulevard (towards PIE). I spotted another car - SHB5470M stopped ahead of me. So I applied my brakes, but just before my car came to a stop, I felt an impact from the rear and the impact caused my car to surge forward and collide with SHB5470M. I checked and discovered that another car - SLL1785G had collided on to the rear of my car. There is a camera installed at the front of my car.



**SINGAPORE  
POLICE FORCE**



T/20200130/2054

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

3 of 4

Report No. T/20200130/2054

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20200130/2054

4 of 4

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999


Report No. T/20200130/2054





CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LOKMAN BIN ABDUL GHANI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/01/2020 12:59
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case: <div style="border: 1px solid black; padding: 5px; display: inline-block;">  <span style="margin-left: 10px;">SINGAPORE POLICE FORCE</span> <span style="float: right; margin-right: 10px;">SN 061</span> </div>
Authentication Stamp NP168	<div style="border: 1px solid black; padding: 5px; display: inline-block;">           SIGNATURE       </div>



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 30-Jan-20

INSURANCE: MSIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH9637L

Description	Qty	List Price	Amount
Bonnet <i>HW</i>	1 X	\$ 2,253.80	\$ 2,253.80
Radiator Grille <i>CRACK</i>	1 ✓	\$ 1,227.50	\$ 1,227.50
Front Bumper Cover <i>distorted / CRACK</i>	1 ✓	\$ 418.30	\$ 418.30
Front Bumper Sponge/Absorber <i>HW</i>	1 X	\$ 86.90	\$ 86.90
Front Bumper Reinforcement <i>Dented</i>	1 ✓	\$ 1,075.10	\$ 1,075.10
Front Bumper Grille (LH/RH) <i>HW</i>	2 X	\$ 186.90	\$ 373.80
Front Bumper Moulding Centre Upper (LH/RH) <i>NH</i>	2 X	\$ 108.50	\$ 217.00
Front Bumper Lower Stiffner <i>HW</i>	1 X	\$ 85.10	\$ 85.10
Front Bumper Bracket Top (LH/RH) <i>NH</i>	2 X	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>NH</i>	2 X	\$ 28.00	\$ 56.00
Front Bumper Side Bracket Support <i>HW</i>	2 X	\$ 12.00	\$ 24.00
Front Bumper Clips 10 pcs <i>HW</i>	1 ✓	\$ 22.00	\$ 22.00
Front Bumper Strip Assy <i>HW</i>	1 X	\$ 29.40	\$ 29.40
Front Bumper Centre Grille <i>NH</i>	1 X	\$ 318.80	\$ 318.80
Headlamp Support Panel Assy <i>CRACK</i>	1 ✓	\$ 949.30	\$ 949.30
Headlamp(LH/RH) <i>CRACK</i> 1198.80 x 2 <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">2397.60</span>	2 ✓	\$ <del>3,987.30</del>	\$ <del>7,974.60</del>
Boot Lid <i>HW</i>	1 ✓	\$ 2,480.40	\$ 2,480.40
Boot Lid Rubber <i>NH</i>	1 ✓	\$ 127.40	\$ 127.40
Boot Lid Hinge (LH/RH) <i>HW</i>	2 X	\$ 31.30	\$ 62.60
Boot Lid Lock Upper <i>Dent</i>	1 ✓	\$ 224.00	\$ 224.00
Boot Lid Lock Lower <i>NH</i>	1 X	\$ 79.80	\$ 79.80
Boot Lid 'H' Emblem <i>NH</i>	1 ✓	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>NH</i>	1 ✓	\$ 24.30	\$ 24.30
Emblem-Ionic <i>NH</i>	1 ✓	\$ 31.30	\$ 31.30
Emblem-Blue Drive(LH/RH) <i>NH</i>	1 X	\$ 26.60	\$ 26.60
Boot Lid Glass, Lower with moulding <i>NH</i>	1 X	\$ 384.90	\$ 384.90
Boot Lid Lamp(LH/RH) <i>NH</i>	2 X	\$ 794.40	\$ 1,588.80
Bootlid Garnish <i>NS</i>	1 X	\$ 36.10	\$ 36.10
Bootlid Lower Garnish <i>NH</i>	1 X	\$ 25.40	\$ 25.40
Rear Bumper <i>CRACK / distorted</i>	1 ✓	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>CRACK / Dented</i>	1 ✓	\$ 294.80	\$ 294.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>	1 X	\$ 138.10	\$ 138.10
Rear Bumper Centre Moulding Assy <i>CRACK</i>	1 ✓	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>NH</i>	1 X	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>NH</i>	1 X	\$ 138.10	\$ 138.10
Rear Bumper Side Bracket (LH/RH) <i>NH</i>	2 X	\$ 55.80	\$ 111.60
Rear Bumper Cover Clips <i>NH</i>	1 ✓	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>NH</i>	1 X	\$ 53.85	\$ 53.85
Rear Bumper Side Under(LH/RH) <i>HW CRACK O/S NH</i>	2 ✓	\$ <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">33.10</span>	\$ 66.20
Rear Bumper Rear Hook <i>NH</i>	1 X	\$ 5.40	\$ 5.40
Rear Bumper Reflector Lamp(LH/RH) <i>NH</i>	2 X	\$ 31.90	\$ 63.80
Rear Bumper Fog Lamp <i>broken</i>	1 ✓	\$ 201.50	\$ 201.50



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 2-Mar-20


INSURANCE: \_\_\_\_\_

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH9637L

Description	Qty	List Price	Amount
Front Speaker Assy <i>CRUC</i>	1	\$ 354.40	\$ 354.40
Unit Assy-SMART CRU (Radar Sensor) <i>Dem / memory broken</i>	1	\$ 2,910.90	\$ 2,910.90
Radiator <i>Vst</i>	1	\$ 510.50	\$ 510.50
Horn Unit (RH) <i>CRUC</i>	1	\$ 72.80	\$ 72.80
Aircon Condenser <i>Punctured / Vst</i>	1	\$ 663.60	\$ 663.60
<b>SUB TOTAL</b>			<b>\$ 4,512.20</b>
<b>LESS 20%</b>			<b>\$ 902.44</b>
<b>DISCOUNTED TOTAL</b>			<b>\$ 3,609.76</b>
<b>ESTIMATE TOTAL</b>			<b>\$ 3,609.76</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared			

✓  
✓  
✓  
✓

  
*Ryan*  
 Lkk Auto

9

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2020		06 Feb 2020 15:45 <a href="#">Edit Adj Rpt</a>	<b>S\$13,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$13,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE.LTD.</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SH9637L</b>	Date of Loss:	29/01/2020 23:00 - :59 [17 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 618962</b>	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	<b>SLL1785G</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>Bifrost Auto Pte Ltd (sin Ming) (HQ)</b> Blk 9 Sector C, #01-42 Sin Ming Industrial Estate, 575644 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 07/03/2020]								
Driver/Custodian (Insured):	BRANDON TAN (24 / Male) , NRIC: S9505015H, Tel: +6596736555 Email:								
Adj Asg. Remarks:	(MANUAL ASSIGN). on WP. Oi:Grab. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lee @ 9792 1329.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

\*SH9637L (618962)  
 [SLL1785G]  
 TP  
**COMFORT TRANSPORTATION PTE LTD**  
 Jan 29 2020 11:00PM  
 [GRAB RENTALS PTE.LTD.]  
 Bifrost Auto Pte Ltd (sin Ming)

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
<b>Assessment Reports</b>				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/20 11:04	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>				3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/02/20 13:03	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
2	29/02/20 13:03	Rear View Left	Load JPG	<input checked="" type="checkbox"/>
3	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
4	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
5	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
6	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
7	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
8	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
9	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
10	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
11	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
12	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
13	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
14	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
15	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
16	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
17	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
18	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
19	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
20	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
21	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
22	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
23	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
24	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
25	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
26	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
27	29/02/20 13:03	General View	Load JPG	<input checked="" type="checkbox"/>
28	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
29	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
30	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
31	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
32	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
33	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>
34	29/02/20 13:04	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
				<input checked="" type="checkbox"/>
35	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
36	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
37	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
38	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
39	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
40	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
41	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
42	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
43	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
44	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
45	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
46	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
47	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
48	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
49	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
50	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
51	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
52	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
53	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
54	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
55	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
56	29/02/20 13:04	Front View Left		<input checked="" type="checkbox"/>
57	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
58	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
59	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
60	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
61	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
62	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
63	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
64	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
65	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
66	29/02/20 13:04	General View		<input checked="" type="checkbox"/>
67	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
68	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
69	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
70	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
71	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
72	29/02/20 13:05	General View		<input checked="" type="checkbox"/>
73	29/02/20 13:05	Odometer Reading		<input checked="" type="checkbox"/>
74	29/02/20 13:05	Chassis Number		<input checked="" type="checkbox"/>
75	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
76	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
77	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
78	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
79	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
80	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
81	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
82	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>
83	29/02/20 13:07	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	29/02/20 13:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
131	29/02/20 13:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
132	29/02/20 13:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
133	29/02/20 13:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	29/02/20 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	29/02/20 13:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
181	29/02/20 13:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
182	29/02/20 13:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
183	29/02/20 13:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	29/02/20 13:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
216	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
217	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
218	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
219	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
220	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
221	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
222	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
223	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
224	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
225	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
226	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
227	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
228	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
229	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
230	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
231	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
232	29/02/20 13:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)	1 per page	<input checked="" type="checkbox"/>
Documentation			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
1	06/02/20 13:55	<b>TPD SH9637J GIA REPORT</b> From:SC - Reg. No: SLL1785G, Claimant: GRAB RENTALS PTE.LTD.	Load PDF	
2	06/02/20 13:56	<b>TPD SH9637J - PRI</b>	Load PDF	
3	06/02/20 14:09	<b>Agree on SJE</b>	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		
1	06/02/20 15:40	<b>email - Manual Assign</b>	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	03/04/20 10:28	<b>Supplementary</b>	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20002063/DYF3E2  
**Date:** 03/04/2020

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29114756MKF	
Claimant Vehicle No: SH9637L	Insured Vehicle No: SLL1785G	
Date of Loss: 29/01/2020	Nature of Claim: TP	Claim No: 618962

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SH9637L</b>	Engine No: G4LEJU076120	
Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No: KMHC851CVKU106502	
Reg. Date: 15/08/2018 (Man. Year: 2018)	Odometer: 225482 km	
Colour: Blue		
Engine Capacity: 1580 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15
Front Left Side: DURATURN 5 mm	Rear Left Side: DURATURN 5 mm
Front Right Side: DURATURN 5 mm	Rear Right Side: DURATURN 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,370.52	15,167.64	11,202.88	42.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,240.00	2,410.00	51.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,020.52</b>	<b>17,407.64</b>	<b>13,612.88</b>	<b>43.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,900.00</b>		
	(S\$) 31,020.52	13,900.00	17,120.52	55.19
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,171.44</b>	<b>973.00</b>	<b>1,198.44</b>	<b>55.19</b>
<b>Nett Amount (S\$)</b>	<b>33,191.96</b>	<b>14,873.00</b>	<b>18,318.96</b>	<b>55.19</b>

#### INSPECTION

Date of Assignment:	06/02/2020	
Date Inspected:	06/02/2020 Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644

Estimated Period of Repair: 11.0 days

---

**Adjuster:** BRYAN TANI

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 03 Apr 2020)
<b>Parts:</b>	N/A HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH9637L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,253.80 FL	*- FL
2	1		*RADIATOR GRILLE	Cracked	1,227.50 FL	*1,227.50 FL
3	1		*FRONT BUMPER COVER	Distorted / Cracked	418.30 FL	*418.30 FL
4	1		*FRONT BUMPER SPONGE / ABSORBER	Not Necessary	86.90 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	1,075.10 FL	*1,075.10 FL
6	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	373.80 FL	*- FL
7	2		*FRONT BUMPER MOULDING CENTRE UPPER (LH/RH)	Not Necessary	217.00 FL	*- FL
8	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	85.10 FL	*- FL
9	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
10	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	56.00 FL	*- FL
11	2		*FRONT BUMPER SIDE BRACKET SUPPORT	Not Necessary	24.00 FL	*- FL
12	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
13	1		*FRONT BUMPER STRIP ASSY	Not Necessary	29.40 FL	*- FL
14	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	318.80 FL	*- FL
15	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	949.30 FL	*949.30 FL
16	2		*HEADLAMP (LH/RH)	Cracked	7,974.60 FL	*2,397.60 FL
17	1		*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
18	1		*BOOT LID RUBBER	Necessary	127.40 FL	*127.40 FL
19	2		*BOOT LID HINGE (LH/RH)	Not Necessary	62.60 FL	*- FL
20	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
21	1		*BOOT LID LOCK LOWER	Repair	79.80 FL	*- FL
22	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
23	1		*EMBLEM - HYBRID	Necessary	24.30 FL	*24.30 FL
24	1		*EMBLEM - IONIQ	Necessary	31.30 FL	*31.30 FL
25	1		*EMBLEM - BLUE DRIVE (LH/RH)	Not fitted	26.60 FL	*- FL
26	1		*BOOT LID GLASS, LOWER WITH MOULDING	Not Necessary	384.90 FL	*- FL
27	2		*BOOT LID LAMP (LH/RH)	Not Necessary	1,588.80 FL	*- FL
28	1		*BOOTLID GARNISH	No such part	36.10 FL	*- FL
29	1		*BOOTLID LOWER GARNISH	No such part	25.40 FL	*- FL
30	1		*REAR BUMPER	Cracked / Distorted	459.40 FL	*459.40 FL
31	1		*REAR BUMPER REINFORCEMENT	Cracked / Dented	294.80 FL	*294.80 FL
32	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	138.10 FL	*- FL
33	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
34	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	47.50 FL	*- FL
35	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
36	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	111.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
38	1		*REAR BUMPER UNDER CENTRE	Not Necessary	53.85 FL	*- FL
39	1		*REAR BUMPER SIDE UNDER (LH/RH)	N/S Cracked / O/S Not Necessary	66.20 FL	*33.10 FL
40	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	63.80 FL	*- FL
41	1		*REAR BUMPER FOG LAMP	Broken	201.50 FL	*201.50 FL
42	1		*REAR BUMPER TOWING COVER	Serviceable	98.80 FL	*- FL
43	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Not Necessary	257.10 FL	*- FL
44	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,740.80 FL	*1,740.80 FL
45	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
46	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
47	1		*REAR PANEL GARNISH	Mtg Deformed	376.80 FL	*376.80 FL
48	1		*REAR PANEL LOWER PANEL	Not Necessary	39.40 FL	*- FL
49	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
50	1		*SPARE TYRE PANEL	Dented	892.50 FL	*892.50 FL
51	1		*EXHAUST PIPE INSULATOR	Not Necessary	35.00 FL	*- FL
52	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
53	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
54	1		*REAR WINDSCREEN MOULDING	Not Necessary	48.50 FL	*- FL
55	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FL	*46.00 FL
56	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
57	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
58	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
59	1		*BOOT LID COMFORT LOGO STICKER	Necessary	8.60 FS	*8.60 FS
60	1		*BOOT LID COMFORT CABLINK TEL NO. STICKER	Not Necessary	9.00 FS	*- FS
61	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*45.00 FS
62	1		*FRONT NO PLATE TRIM COVER }	Broken	30.00 FS	*- FS
63	1		*FRONT SPEAKER ASSY	Cracked	354.40 FL	*354.40 FL
64	1		*UNIT ASSY - SMART CRU (RADAR SENSOR)	Damaged / Mtg Broken	2,910.90 FL	*2,910.90 FL
65	1		*RADIATOR	Bent	510.50 FL	*510.50 FL
66	1		*HORN UNIT (RH)	Cracked	72.80 FL	*72.80 FL
67	1		*AIRCON CONDENSER	Punctured / Bent	663.60 FL	*663.60 FL
68	1		*REAR BUMPER REAR HOOK	Not Necessary	5.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>32,880.00</b>	<b>18,881.15</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>6,509.48</b>	<b>3,713.51</b>
<b>Total Parts (S\$)</b>	<b>26,370.52</b>	<b>15,167.64</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	180.00	40.00
5	TOWING CHARGE	New	60.00	0.00
6	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE / REFIX RADIATOR	New	90.00	50.00
9	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	320.00
<b>Gross Labour Cost (S\$)</b>			<b>4,650.00</b>	<b>2,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >