



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 9302Y

| Qty   | Description of Parts   | Condition           | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b>  |  |                     |                           |                   |
| 1   | FRONT BUMPER   | DEFORMED            | 1,899.50                  | 1,510.00          |
| 2   | FRONT BUMPER SIDE RETAINER @\$120.30                               | O/S NECESSARY       | 240.60                    | 120.30            |
| 2   | FRONT BUMPER SENSOR @\$268.00                                      | DAMAGED (1 PC ONLY) | 536.00                    | 268.00            |
| 1   | FRONT BUMPER LOWER GRILLE  | CRACKED             | 260.00                    | 260.00            |
| 1   | FRONT HEADLAMP (HID)   | CUT                 | 3,600.00                  | 3,059.00          |
| 1   | FRONT HEADLAMP TOP RUBBER  | NOT NECESSARY       | 140.00                    | -                 |
|   | LESS 10% DISCOUNT  |                     | -667.61                   | -521.73           |
|   |  |                     | 6,008.49                  | 4,695.57          |
| <b><u>SPECIAL NETT ITEMS</u></b>  |  |                     |                           |                   |
| 1   | SET FRONT HEADLAMP CLIP (SN)                                       | NECESSARY           | 20.00                     | 20.00             |
| 1   | LOWER LID (SN)   | CRACKED             | 2,500.00                  | 1,200.00          |
|   |  |                     | 2,520.00                  | 1,220.00          |
| <b><u>LABOUR</u></b>  |  |                     |                           |                   |
|   | PANEL BEATING,WELDING,CUTTING,GRAZING<br>ADJUST,KNOCK STRAIGHTEN.  |                     | 1,000.00                  | 300.00            |
|   | TO PUTTY,SPRAY PAINT,POLISH,WAX.                                   |                     | 1,000.00                  | 250.00            |
|   | TO APPLY RUST PROOFING/UNDER COAT.                                 | NOT NECESSARY       | 250.00                    | -                 |
|   | WIRING,BULB CHECKING.  |                     | 120.00                    | 30.00             |
|   | REFOCUS HEADLAMP BEAM.   | NOT NECESSARY       | 150.00                    | -                 |
|   | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT/CONTROL UNITS,RESET. | NOT NECESSARY       | 500.00                    | -                 |
|   |  |                     | 3,020.00                  | 580.00            |
| <b>GRAND TOTAL</b>  |  |                     | <b>11,548.49</b>          | <b>6,495.57</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |                     |                           | <b>5,100.00</b>   |

Report Ref No. CS/AGI20002073/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.