

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20002077/NTF3E2

Date: 09/09/2020

REFERENCE

Insured/Claimant:	ASLINA BINTE ABDULLAH	Policy No:	1900158439
Date of Loss:	04/02/2020	Nature of Claim:	OD
		Claim No:	1981366532SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM2500T	Engine No:	G3E6E0289927
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740H0053501
Reg. Date:	07/09/2017 (Man. Year: 2017)	Odometer:	46039 km
Colour:	Yellow		
Engine Capacity:	150 cc		
Market Value/New Car Price:	S\$7,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	120/70 R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Duro 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,726.50	3,558.00	1,168.50	24.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	450.00	1,200.00	72.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,376.50	4,008.00	2,368.50	37.14
Approved Total (Overridden) (\$\$)		2,800.00		
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	6,076.50	2,500.00	3,576.50	58.86
+ GST 7.00/7.00% (\$\$)	425.36	175.00	250.36	58.86
Nett Amount (\$\$)	6,501.86	2,675.00	3,826.86	58.86

INSPECTION

Date of Assignment:	06/02/2020	Inspected At:	Bike Production (HQ) No 610 Serangoon Road Singapore 218216
Date Inspected:	06/02/2020		
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DISK	Serviceable	140.00 FL	*- FL
2	1		*FRONT WHEEL AXLE	Serviceable	75.00 FL	*- FL
3	1		*RIGHT FORK ASSEMBLY	Serviceable	390.00 FL	*- FL
4	1		*FRONT FAIRING COVER INNER	Scratched	150.00 FL	*150.00 FL
5	1		*LEFT FAIRING ASSEMBLY	Scratched	270.00 FL	*270.00 FL
6	1		*RIGHT FAIRING ASSEMBLY	Cracked	270.00 FL	*270.00 FL
7	1		*LEFT FAIRING ASSEMBLY LABELS	Necessary	65.00 FL	*65.00 FL
8	1		*RIGHT FAIRING ASSEMBLY LABELS	Necessary	65.00 FL	*65.00 FL
9	1		*LOWER CENTRE FAIRING	Deformed	120.00 FL	*120.00 FL
10	2		*YAMAHA AMBLEM	Necessary	40.00 FL	*20.00 FL
11	1		*CENTER BOX	Scratched	80.00 FL	*80.00 FL
12	1		*BRAKE PUMP ASSY	Scratched	145.00 FL	*145.00 FL
13	1		*RIGHT SIGNAL ASSY	Missing	65.00 FL	*65.00 FL
14	2		*STEERING STEM BEARING	Serviceable	90.00 FL	*- FL
15	1		*STEERING STEM BRACKET ASSEMBLY	Serviceable	195.00 FL	*- FL
16	1		*HANDLE BAR	Serviceable	135.00 FL	*- FL
17	1		*CLUTCH LEVER	Scratched	40.00 FL	*40.00 FL
18	1		*BRAKE LEVER	Scratched	40.00 FL	*40.00 FL
19	1		*LEFT VIEW MIRROR	Scratched	40.00 FL	*40.00 FL
20	1		*RIGHT VIEW MIRROR	Serviceable	40.00 FL	*- FL
21	1		*RIGHT BALANCER	Serviceable	35.00 FL	*- FL
22	1		*GEAR PEDAL ASSY	Scratched	95.00 FL	*95.00 FL
23	1		*RIGHT REAR SIGNAL	Bent	65.00 FL	*65.00 FL
24	1		*LEFT REAR FOOTREST	Scratched	45.00 FL	*45.00 FL
25	1		*RIGHT REAR FOOTREST	Serviceable	45.00 FL	*- FL
26	1		*FRONT FOOTREST HOLDER ASSEMBLY	Bent	145.00 FL	*145.00 FL
27	1		*EXHAUST ASSY	Dented	380.00 FL	*380.00 FL
28	1		*LEFT FRONT FOOTREST	Scratched	45.00 FL	*45.00 FL
29	1		*RIGHT FRONT FOOTREST	Bent	45.00 FL	*45.00 FL
30	1		*BRAKE PEDAL ASSY	Bent	75.00 FL	*75.00 FL
31	1		*TOP BOX	Scratched	250.00 FS	*250.00 FS
32	1		*REAR BOX RACK	Serviceable	120.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
34	1		*TOP HEADLIGHT COVER	Cracked	45.00 FL	*45.00 FL
35	1		*BODY COVER BLACK	Scratched	130.00 FL	*130.00 FL
36	1		*FRONT BODY OUTER COVER DECALS	Necessary	45.00 FL	*45.00 FL
37	1		*FRONT BODY OUTER COVER	Cracked	120.00 FL	*120.00 FL
38	1		*FRONT MUDGUARD	Cracked	95.00 FL	*95.00 FL
39	1		*INNER CENTER SILVER	Cracked	55.00 FL	*55.00 FL
40	1		*INNER CENTER BLACK	Cracked	65.00 FL	*65.00 FL
41	1		*LEFT SIGNAL FRONT	Scratched	65.00 FL	*65.00 FL
42	1		*RIGHT LOWER COVER	Cracked	120.00 FL	*120.00 FL
43	1		*SIDE INNER LEFT	Scratched	40.00 FL	*40.00 FL
44	1		*SIDE INNER RIGHT	Missing	40.00 FL	*40.00 FL
45	2		*LEFT BALANCER	Scratched	35.00 FL	*35.00 FL
46	1		*LEFT FORK ASSY	Scratched	390.00 FL	*390.00 FL
47	1		*METER INNER COVER	Deformed	55.00 FL	*55.00 FL
48	2		*METER OUTER COVER	Deformed	55.00 FL	*55.00 FL
49	1		*FRONT NO PLATE	Necessary	20.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	5,205.00	3,920.00
			- List Item Discount on L Items 10.00/10.00% (\$)		478.50	362.00
				Total Parts (\$)	4,726.50	3,558.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	80.00	0.00
2	DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	700.00	300.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	50.00
5	TO REMOVE / REFIT AND BALANCE FRONT SPORT RIM	New	60.00	0.00
6	SPRAY PAINTING	New	250.00	100.00
Gross Labour Cost (S\$)			1,650.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >