

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2004770

INV Date 07/07/2020

Reference CC6/CTI20002090/Uka3n2

Code CT



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJF 8266Y

Insured Veh. GBJ 4794P

Claim No. SNM20D200686

Policy No. DMCVSN1919281900

Accident Date 04/02/2020

Inspection Date 06/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

CHINA TAIPING INSURANCE (S) PTE LTD  Ref : CC6/CTI20002090/Uka3n2  3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 Code : CTI  1.	Affiliated to Federation Internationale Des Experts En Automobile			
SPRINGLEAF TOWERSINGAPORE 079909				
Insured Veh.   GBJ 4794P   Veh. Inspected   SJF 8266Y				
Policy No.   DMCVSN1919281900   Coverage (\$)   0.00				
Claim No.   SNM20D200686   Excess (\$)   0.00     Assign From   Assign Date   06/02/2020				
Assign From   Assign Date   06/02/2020				
Z.         Vehicle Particulars & Condition           Make & Model         HYUNDAL AVANTE (A)         c.c         1591           Engine No.         HIDDEN         Year of Reg.         2008           Chassis No.         KMHDU41BR8U521832         Colour         RED           Odometer         132909         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         GOOD           3.         Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
Make & Model         HYUNDAL AVANTE (A)         c.c         1591           Engine No.         HIDDEN         Year of Reg.         2008           Chassis No.         KMHDU41BR8U521832         Colour         RED           Odometer         132909         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         GOOD         Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
Engine No.         HIDDEN         Year of Reg.         2008           Chassis No.         KMHDU41BR8U521832         Colour         RED           Odometer         132909         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         GOOD         Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
Chassis No.   KMHDU41BR8U521832   Colour   RED				
Odometer         132909         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         GOOD         GOOD           3.         Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
Brakes				
General GOOD				
Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
Size   Make   Balance     R/H Front Tyre   195/60 R15   VIKING   6 mm     L/H Front Tyre   195/60 R15   VIKING   6 mm				
R/H Front Tyre         195/60 R15         VIKING         6 mm           L/H Front Tyre         195/60 R15         VIKING         6 mm				
L/H Front Tyre 195/60 R15 VIKING 6 mm				
Tarriton 1910				
L/H Rear Tyre 195/60 R15 VIKING 6 mm				
Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date 04/02/2020 Inspection Date 06/02/2020				
Survey held at KAI LIANG MOTOR SERVICE				
BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY @KAKI BUKIT SINGAPORE 417883				
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 8266Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR N/S	BADLY DENTED	1,038.40	1,038.40
1	FRONT DOOR OUTER HANDLE N/S	CUT	185.50	185.50
1	FRONT DOOR OUTER GLASS MOULDING N/S	NOT NECESSARY	96.80	-
1	FRONT DOOR INNER LOCK N/S	SHORTED	266.50	266.50
1	FRONT DOOR INNER TRIM BOARD N/S	NOT NECESSARY	488.20	-
1	FRONT DOOR GLASS REGULATOR & MOTOR N/S	NOT NECESSARY	365.30	-
1	SET FRONT DOOR FRAME BLACK STICKER N/S	NECESSARY	65.00	65.00
1	REAR DOOR N/S	BADLY DENTED	1,022.40	1,022.40
1	REAR DOOR OUTER HANDLE N/S	CUT	175.50	175.50
1	REAR DOOR GLASS MOULDING N/S	NOT NECESSARY	95.20	-
1	REAR DOOR INNER LOCK N/S	SHORTED	266.50	266.50
1	REAR DOOR INNER TRIM BOARD N/S	NOT NECESSARY	481.50	-
1	REAR DOOR GLASS REGULATOR & MOTOR N/S	JAMMED	385.00	385.00
1	REAR DOOR FRAME BLACK STICKER N/S	NECESSARY	60.00	60.00
1	CENTRE PILLAR N/S	BADLY DENTED	1,505.20	699.20
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	88.20	-
1	REAR BUMPER	CUT	486.90	486.90
1	REAR BUMPER SIDE RETAINER N/S	NOT NECESSARY	48.20	-
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	245.00	-
1	REAR SPORT RIM N/S	CUT	450.00	450.00
1	REAR WINDSCREEN SEALANT	NOT NECESSARY	50.00	-
	LESS 20% DISCOUNT		-	-1,029.18
			7,910.30	4,116.72
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO TRANSFER BOTH DOOR MECHANISM .		180.00	120.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX REVERSE SENSOR .		80.00	50.00
	TO SPRAY RUST PROOFING .		100.00	80.00

Report Ref No. CC6/CTI20002090/Uka3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT .		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	1,000.00
			3,290.00	2,140.00
	GRAND TOTAL		11,200.30	6,256.72

R	ECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(Τ	TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI20002090/Uka3n2

CHUA KANG SENG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJF 8266Y

#### INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJF 8266Y


### RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJF 8266Y

### RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315



