Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### **VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CC4/FWD20002091/UGA3Q2

**Date:** 11/05/2020

**REFERENCE** 

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00002355

Claimant
Valida No : SJE2990J Insured Vehicle No : SLW9376T

Vehicle No: SJE2990J Insured vehicle No: SLW93761

Date of Loss: 25/01/2020 Nature of Claim: TP Claim No: 1202000005533

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJE2990J

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4745081

Reg. Date: 21/04/2008 (Man. Year: 2008) Chassis No: MR053ZEE106102785

Colour: Beige Odometer: 246732 km

Engine Capacity: 1598 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,544.85	1,405.35	139.50	9.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,000.00	550.00	35.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,094.85	2,405.35	689.50	22.28
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,094.85	1,900.00	1,194.85	38.61
+ GST 7.00/7.00% (S\$)	216.64	133.00	83.64	38.61
Nett Amount (S\$)	3,311.49	2,033.00	1,278.49	38.61
+ Loss of Use (3.0 x S\$	60.00/day) (S\$)	180.00		
+ Doc/Search Fee (S\$)  Nett Liability (S\$)  Global Sum Settlement (S\$)		31.00		
		2,244.00		
		2,240.00		

**INSPECTION** 

Date of Assignment: 06/02/2020

Date Inspected: 06/02/2020 Inspected At: Focus Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #02-48/50 Autobay

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)		
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SJE2990J)			
Validity:	<b>dity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Buckled	652.20 FL	*565.10 FL
2	1		*FRONT FENDER DUST COVER -RH	Torn	126.40 FL	*126.40 FL
3	1		*FRONT FENDER EMBLEM -RH	Necessary	28.20 FL	*28.20 FL
4	8		*FRONT FENDER DUST CLIPS -RH	Necessary	44.00 FL	*44.00 FL
5	1		*FRONT HEADLAMP -RH	Scratched	543.90 FL	*543.90 FL
6	1		*FRONT WASHER TANK	Serviceable	98.90 FL	*- FL
7	1		*FRONT BUMPER	Torn	481.60 FL	*481.60 FL
8	1		*FRONT BUMPER SIDE RETAINER	Bent / Cracked	51.60 FL	*51.60 FL
9	6		*FRONT BUMPER CLIPS	Necessary	33.00 FL	*33.00 FL
F=Fra	F=Franchise part. L=ListItemDisc.  Sub Total (S\$)  - List Item Discount on L Items 25.00/25.00% (S\$)				<b>2,059.80</b> 514.95	<b>1,873.80</b> 468.45
				Total Parts (S\$)	1,544.85	1,405.35
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	750.00	350.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	SPRAY PAINTING	New	680.00	600.00
		Gross Labour Cost (S\$)	1,550.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >