4/19/22, 5:55 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20002097/KGA3Q2

19/04/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549

Claimant Vehicle SHD5670S Insured Vehicle No: GBH7498K

No:

Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: MFL2020D0000364

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD5670S

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2C00095 Engine No:

Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: JTDKB3FU803079222

Metallic Pearl White/Red Odometer: 86160 km Colour:

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Yokohama 9 mm Yokohama 9 mm Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 9,403.27 | 427.95 | 8,975.32 | 95.45 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,170.00 | 540.00 | 13,630.00 | 96.19 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 23,573.27 | 967.95 | 22,605.32 | 95.89 |
| + GST 7.00/7.00% (S\$) | 1,650.13 | 67.76 | 1,582.37 | 95.89 |
| Nett Amount (S\$) | 25,223.40 | 1,035.71 | 24,187.69 | 95.89 |

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 05/02/2020

Trans-cab Auto Services Pte Ltd Date Inspected: 05/02/2020 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

KENNETH KONG Manager: Chong Pui Lin Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHD5670S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|--------------|----------------------------------|-------------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented / Cut | 442.60 FL | *442.60 FL |
| 2 | 1 | | *REAR BUMPER REINFORCEMENT | Repair | 332.70 FL | *- FL |
| 3 | 1 | | *REAR BUMPER TOWING COVER | Serviceable | 15.40 FL | *- FL |
| 4 | 1 | | *GUARD ,REAR BUMPER CENTER | Serviceable | 576.30 FL | *- FL |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER LH | Serviceable | 116.50 FL | *- FL |
| 6 | 1 | | *REAR BUMPER SIDE RETAINER RH | Serviceable | 117.70 FL | *- FL |
| 7 | 1 | | *REAR TAILGATE | Repair | 1,147.80 FL | *- FL |
| 8 | 1 | | *REAR TAILGATE OUTER GARNISH | Serviceable | 925.60 FL | *- FL |
| 9 | 1 | | *REAR TAILGATE WEATHERSTRIP | Serviceable | 372.30 FL | *- FL |
| 10 | 1 | | *PANEL SUB-ASSY ,BODY LOWER BACK | Repair | 650.30 FL | *- FL |
| 11 | 1 | | *TAILLAMP LOWER RH | Serviceable | 502.00 FL | *- FL |
| 12 | 1 | | *TAILLAMP UPPER RH | Serviceable | 451.80 FL | *- FL |
| 13 | 1 | | *REAR BUMPER SIDE RH | Serviceable | 123.70 FL | *- FL |
| 14 | 1 | | *REAR BUMPER SIDE LH | Serviceable | 123.70 FL | *- FL |
| 15 | 1 | | *TAILLAMP LOWER LH | Serviceable | 502.00 FL | *- FL |
| 16 | 1 | | *TAILLAMP UPPER LH | Serviceable | 443.30 FL | *- FL |
| 17 | 1 | | *COVER ,DECK TRIM ,REAR | Serviceable | 126.70 FL | *- FL |
| 18 | 1 | | *COVER ,FLOOR UNDER NO.1 | Serviceable | 175.10 FL | *- FL |
| 19 | 1 | | *COVER ,FLOOR UNDER NO.2 | Serviceable | 241.90 FL | *- FL |
| 20 | 1 | | *COVER ,REAR FLOOR | Serviceable | 229.90 FL | *- FL |
| 21 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 22 | 1 | | *SET REAR BUMPER CLIP | Necessary | 66.00 FS | *66.00 FS |
| 23 | 1 | | *REAR TAILGATE TOYOTA LOGO | Not Necessary | 47.00 FS | *- FS |
| 24 | 1 | | *REAR TAILGATE WORDING PRIUS | Not Necessary | 52.90 FS | *- FS |
| 25 | 1 | | *REAR TAILGATE WORDING HYBRID | Not Necessary | 53.50 FS | *- FS |
| 26 | 1 | | *REAR TAILGATE STICKER TRANS-CAB | Not Necessary | 80.00 FS | *- FS |
| 27 | 1 | | *REAR TAILGATE STICKER 6555-3333 | Not Necessary | 80.00 FS | *- FS |
| 28 | 1 | | *REAR BUMPER PROTECTOR | Necessary | 100.00 FS | *30.00 FS |
| 29 | 1 | | *REAR WHEEL RIM | Serviceable | 1,879.40 FS | *- FS |
| 30 | 1 | | *REAR TYRE 195/65/15 | Serviceable | 350.00 FS | *-FS |
| 31 | 1 | | *REAR WHEEL RIM COVER | Serviceable | 211.50 FS | *- FS |
| 32 | 1 | | *REAR RH BUMPER RETAINER CLIP | Not Necessary | 35.00 FS | *- FS |
| 33 | 1 | | *REAR LH BUMPER RETAINER CLIP | Not Necessary | 35.00 FS | *-FS |
| F=Fra | anchise | part. S=SpcN | ett. L=ListItemDisc. | - | | |
| | | | Little Harris Billion Co. | Sub Total (S\$) | 11,307.60 | 538.60 |
| | - List Item Discount on L Items 25.00/25.00% (S\$) | | | | 1,904.33 | 110.65 |
| | | | | Total Parts (S\$) | 9,403.27 | |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------|--|------------|------------|--------|
| Labo | our Items | | | |
| 1 | TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | New | 170.00 | 0.00 |
| 2 | TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | New | 170.00 | 0.00 |
| 3 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 4 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 5 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 6 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 6,000.00 | 280.00 |
| 7 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 0.00 |
| 8 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 50.00 |
| 9 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 10 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 11 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 10.00 |
| 12 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 6,000.00 | 200.00 |
| | Gross Labour | 14,170.00 | 540.00 | |
| | Report was unsubmitted during this | orint-out. | | |

< END OF ESTIMATES >