



Case Details

Case Reference Number :

TAX/02/20/2007

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6031E

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10380-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 04/02/2020 03:30 AM

Vehicle Age(In Months) : 52

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	/ NC
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	X / N/A
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	X / N/A
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give	X / N/A
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X / N/A
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	X R
Standard	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	X / DR
Standard	Main		6505458	LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X / N/A
Standard	Main		6505558	FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	/ DD
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ NC
Standard	Main		6505554	FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	X / N/A
Total Spare Part Cost									1,720.16	Surveyor Total		650.85		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									1,376.13	Final Sur Total		520.68		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			756.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30 / NPC	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20 / NPC	
3	Main	TO REPLACE SUNDRY PARTS	100.00	20 / NPC	
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			340.00	70.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,376.13	520.68 /
Total Labour Cost	507.00	300.00 /
Total Spray Painting	756.00	400.00 /
Other	340.00	70.00 /
Overall Total	2,979.13	1,290.68 /
Lump Sum Repair Option		☒
Lump Sum Total	3,000.00	1,300.00
Surveyor Approved Amount		1,300.00
No of Repair Days*	4	2
Remarks		L/S REPAIR, TAKE AFTER SPRAY

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Signature

STEVE CHEN



Save

Clear

Survey Date

05/02/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: