

Surveyor

Stev

REF:

CTI

ASSIGNMENT

From:

Date:

Veh No:

SHD 6031E

Yr Regn:

23/19/15

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Prius

C.C.

1797

at Workshop m/s

Colour

Maroon

A/C: Insured / Std / NI / NA

of

Sp. Reading

436685

T/Radio: Insured / Std / NI / NA

Insured.

Eng/No:

Policy No.

C/No:

JTDKN36U395766491

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modl: NII / S/Rlm / STD A/Rlm or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR. Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

4/2/20

D.O.I.

5/2/20

Lum Sum:

%

3 Val.: Yes or No

Survey held at

SMRT

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Procl. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. - SI

) P/Bal.

) Others

) ..

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



Case Details

Case Reference Number :
TAX/02/20/2007

Type of Repair : Accident Repair

Vehicle Registration Number :
SHD6031E

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10380-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 04/02/2020 03:30 AM

Vehicle Age(In Months) : 52

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ NK
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X N/A
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	X R
Standard	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	X ✓ DR
Standard	Main		6505458	LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	X N/A
Standard	Main		6505558	FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✓ DD
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓ NK
Standard	Main		6505554	FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									1,720.16	Surveyor Total		650.85		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									1,376.13	Final Sur Total		520.68		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			756.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	✓ APC
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	✓ APC
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ APC
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			340.00	70.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,376.13	520.68 /
Total Labour Cost	507.00	300.00 /
Total Spray Painting	756.00	400.00 /
Other	340.00	70.00 /
Overall Total	2,979.13	1,290.68 /
Lump Sum Repair Option		✓
Lump Sum Total	3,000.00	1,300.00
Surveyor Approved Amount		1,300.00
No of Repair Days*	4	2
Remarks	-	L/S REPAIR, TAKE AFTER SPRAY

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Signature

STEVE CHEN



Save

Clear

Survey Date

05/02/2020

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHD6031E
Case Reference Number	TAX/02/20/2007
Registration Date	23/10/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	AW LYE HUAT
Type of Accident	Head to Rear
Accident Date and Time	4/2/2020 11:30 AM
Accident Reported Date and Time	4/2/2020 1:42 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105579
Special Instruction to ARC, if any	LEFT FRONT PORTION
Prepared Date and Time	5/2/2020 1:31 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$1,376.13	\$520.69
Total Other Cost	\$340.00	\$70.00
TOTAL COST	\$2,979.13	\$1,290.69
Lump Sum Total	\$3,000.00	\$1,300.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	06/02/2020 10:09 AM	05/02/2020 2:45 PM
Signature		
Remarks	L/S REPAIR, TAKE AFTER SPRAY	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2002-0405	Invoice Number	
Quotation Date	20.02.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$340.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given X
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Not Given X
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given X
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair R
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given X
Total					\$2,176.71		\$650.86		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

650.86
- 20%

520.69
+ 300.00
+ 470.00

1290.69

45 \$1300/-