

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20002111/R1HS3Q2**Date:** 07/04/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800150316

Claimant
Vehicle No : SLK7661X **Insured Vehicle No :** SMG675L

Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: 8518232307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7661X	Engine No:	38369764B37C15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2B32070V791757
Reg. Date:	26/01/2017 (Man. Year: 2016)	Odometer:	76052 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,764.60	2,763.60	2,001.00	42.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,149.00	4,780.00	2,369.00	33.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,913.60	7,543.60	4,370.00	36.68
+ GST 7.00/7.00% (S\$)	833.95	528.05	305.90	36.68
Nett Amount (S\$)	12,747.55	8,071.65	4,675.90	36.68
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,473.65		

INSPECTION

Date of Assignment: 17/02/2020

Date Inspected: 17/02/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
3	1		*TRUNK LID	Bent	1,210.35 FS	*1,210.35 FS
4	1		*REAR BUMPER PANEL PRIMED (PDC)	Cut	1,045.45 FS	*1,045.45 FS
5	1		*REAR BUMPER CARRIER	Serviceable	460.40 FS	*- FS
6	1		*SUPPORT	Serviceable	45.55 FS	*- FS
7	1		*RR BUMPER LH INNER SIDE GUIDE	Serviceable	61.35 FS	*- FS
8	1		*RR BUMPER RH INNER SIDE GUIDE	Serviceable	61.35 FS	*- FS
9	1		*SET MOUNTS PDC SENSOR REAR	Serviceable	60.70 FS	*- FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	1		*PLAQUE 74MM	Necessary	71.60 FS	*71.60 FS
12	10		*BUMP STOP	Necessary	37.50 FS	*37.50 FS
13	1		*REAR WINDOW ESG	Not Necessary	657.60 FS	*- FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
15	2		*(DG/SL) W/SCREEN SEAALNT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
16	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
17	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,764.60	2,763.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS ,BOOT LID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	3,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,730.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	119.00	100.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
8	TO SUPPLY AND INSTALL LOADING EDGE PROTECTION PLATE	New	200.00	0.00
Gross Labour Cost (\$)			7,149.00	4,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >