

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20002116/EGS3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMF2799E	Insured Vehicle No :	SHA3942L
Date of Loss: 01/02/2020	Nature of Claim: TP	Claim No: MCT20020001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF2799E		
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Engine No:	41015457B38B15A
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WBA8E320X0A553281
Colour:	Silver	Odometer:	5672 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,608.15	3,608.15	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,987.00	8,172.00	1,815.00	18.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,595.15	11,780.15	1,815.00	13.35
+ GST 7.00/7.00% (S\$)	951.66	824.61	127.05	13.35
Nett Amount (S\$)	14,546.81	12,604.76	1,942.05	13.35
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
Nett Liability (S\$)		13,204.76		

INSPECTION

Date of Assignment:	26/02/2020	
Date Inspected:	26/02/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2020)
Parts:	143	BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF2799E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*REAR LH DOOR	Dented	1,273.85 FS	*1,273.85 FS
3	1		*FRT LH DOOR	Dented	1,273.85 FS	*1,273.85 FS
4	1		*FRT DOOR WEATHERSTRIP	Necessary	141.40 FS	*141.40 FS
5	1		*REAR DOOR WEATHERSTRIP	Necessary	141.40 FS	*141.40 FS
6	1		*REAR LH SIDE WINDOW FIXED	Necessary	172.55 FS	*172.55 FS
7	1		*SUPPORTING LEDGE LH	Broken	36.40 FS	*36.40 FS
8	1		*SUPPORTING LEDGE LH	Broken	37.95 FS	*37.95 FS
9	1		*SUPPORTING LEDGE LH	Broken	37.75 FS	*37.75 FS
10	1		*LH SILL TRIM PRIMED	Broken	324.10 FS	*324.10 FS
11	6		*EXPANDING NUT	Necessary	12.60 FS	*12.60 FS
12	6		*EXPANDING NUT 7X7 MM	Necessary	6.30 FS	*6.30 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,608.15	3,608.15
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPALCING LEFT FRONT DOOR ,LEFT REAR DOOR ,LEFT SIDE SKIRT ,REWORK LEFT FRONT FENDER ,LEFT RUNNING BOARD	New	5,100.00	3,825.00
2	SPRAY LEFT FRONT FENDER ,LEFT FRONT DOOR ,LEFT REAR DOOR ,LEFT SIDE SKIRT ,LEFT RUNNING BOARD AND DOOR HANDLE	New	4,297.00	3,867.00
3	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) X2 PANEL	New	236.00	180.00
Gross Labour Cost (\$\$)			9,987.00	8,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >