

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20002119/FPS3Q2  
**Date:** 02/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800077108
<b>Claimant Vehicle No :</b>	SLS8609A	<b>Insured Vehicle No :</b>	SGF9992M
Date of Loss:	22/01/2020	Nature of Claim:	TP
		Claim No:	9399979073SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLS8609A</b>	Engine No:	LEB5259774
Make & Model:	HONDA GRACE, 1.5 (A)	Chassis No:	GM41109753
Reg. Date:	09/10/2017 (Man. Year: 2017)	Odometer:	49941 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,238.96	2,076.48	162.48	7.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,300.00	680.00	34.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,218.96</b>	<b>3,376.48</b>	<b>842.48</b>	<b>19.97</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		

## Adjuster Report

	(S\$)	4,218.96	2,700.00	1,518.96	36.00
<b>+ GST 7.00/7.00% (S\$)</b>		295.33	189.00	106.33	36.00
<b>Nett Amount (S\$)</b>		<b>4,514.29</b>	<b>2,889.00</b>	<b>1,625.29</b>	<b>36.00</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>			535.00		
	(S\$)		3,424.00		
<b>Liab Amount (90.00%) (S\$)</b>			<b>3,081.60</b>		
<b>+ Doc/Search Fee (S\$)</b>			2.00		
<b>Nett Liability (S\$)</b>			<b>3,083.60</b>		
<b>Global Sum Settlement (S\$)</b>			<b>3,000.00</b>		

INSPECTION

Date of Assignment: 05/02/2020

Date Inspected: 05/02/2020

Estimated Period of Repair: 5.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

**Adjuster:** PARASURAM SHANMUGAM**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*O/S REAR FENDER	Cut	1,134.80 FL	*1,134.80 FL	
2	1		*O/S REAR FENDER INNER COWLING	Not Necessary	85.00 FL	*- FL	
3	6		*O/S REAR FENDER INNER COWLING	Not Necessary	21.00 FL	*- FL	
4	1		*O/S REAR FENDER AIR VENT	Not Necessary	35.70 FL	*- FL	
5	1		*REAR BUMPER	Cracked	463.70 FL	*463.70 FL	
6	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	13.90 FL	*- FL	
7	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*25.00 FL	
8	1		*O/S REAR WHEEL HUB CAP	Scratched	75.00 FL	*75.00 FL	
9	1		*O/S REAR DOOR	Dented	759.60 FL	*759.60 FL	
10	1		*O/S REAR FENDER 1/4 GLASS SEALANT	Necessary	100.00 FS	*70.00 FS	
11	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS	
					<b>Sub Total (\$)</b>	<b>2,763.70</b>	<b>2,568.10</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	524.74	491.62
					<b>Total Parts (\$)</b>	<b>2,238.96</b>	<b>2,076.48</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	50.00
2	TO TRANAFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	100.00	60.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	60.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	450.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	600.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>1,980.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >