Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20002127/ABA3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005121

Claimant SLD7294J Insured Vehicle No: SLZ8076A

Vehicle No: SLD72943 Insured vehicle No: SLZ8076A

Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: 1202000007668

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD7294J

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX581383

Reg. Date: 27/06/2016 (Man. Year: 2016) Chassis No: MR053REH104553095

Colour: Grey Odometer: 235318 km

Engine Capacity: 1598 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,018.84	3,678.58	2,340.26	38.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,800.00	640.00	26.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	8,458.84	5,478.58	2,980.26	35.23
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	8,458.84	4,300.00	4,158.84	49.17
+ GST 7.00/7.00% (S\$)	592.12	301.00	291.12	49.17
Nett Amount (S\$)	9,050.96	4,601.00	4,449.96	49.17
+ Car Rental (5.0 x S\$6	+ Car Rental (5.0 x S\$60.95/day) (S\$)			
+ Doc/Se	7.45			
Net	4,913.20			
Global Sum S	4,800.00			

INSPECTION

Date of Assignment: 06/02/2020

Date Inspected: 24/02/2020 Inspected At: N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster Report Page 2 of 5

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)		
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for SLD7294J)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	781.10 FL	*781.10 FL
2	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	54.10 FL	*54.10 FL
3	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	50.20 FL	*50.20 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	58.50 FL	*58.50 FL
5	2		*REAR BOOTLID HINGES L/R	Not Necessary	159.20 FL	*-FL
6	2		*REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	34.00 FL	*-FL
7	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	181.85 FL	*-FL
8	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	85.00 FL	*-FL
9	1		*REAR BOOTLID MECHANISM LOCK	Damaged	379.20 FL	*379.20 FL
10	1		*REAR BOOTLID WEATHER STRIP	Cut	271.45 FL	*271.45 FL
11	1		*REAR BUMPER	Deformed	581.90 FL	*581.90 FL
12	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	282.90 FL	*-FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	398.70 FL	*398.70 FL
14	2		*REAR BUMPER REINFORCEMENT BRACKET L/R	Bent	330.00 FL	*330.00 FL
15	2		*REAR BUMPER REVERSE SENSOR	Damaged	379.00 FL	*379.00 FL
16	2		*REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	242.20 FL	*-FL
17	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	715.20 FL	*-FL
18	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	130.00 FL	*130.00 FL
19	1		*REAR END PANEL	Dented		*781.90 FL
20	1		*REAR END PANEL INNER TOP GARNISH	Deformed	185.99 FL	*185.99 FL
21	2		*REAR FENDER INNER TRIM L/R	Not Necessary	676.00 FL	*-FL
22	2		*REAR FLOOR PANEL TOP BOARD COVER	Torn	676.00 FL	*292.00 FL
23	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	177.40 FL	*177.40 FL
24	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*-FS
25	1		*SET REAR BOOTLID OUTER CHROME HANDLE CLIP	S Not Necessary	50.00 FS	*-FS
26	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
28	2		*SET REAR FENDER INNER TRIM CLIPS L/R	Not Necessary	100.00 FS	*-FS
F=Fra	anchise	part. S=S	pcNett. L=ListItemDisc.	Sub Total (S\$)	7,921.79	4,891.44
			- List Item Discount on L Items 29		1,902.95	1,212.86
				Total Parts (S\$)	6,018.84	3,678.58

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
	Report was unsubmitted during this print-out.					

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	100.00	80.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	60.00
3	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
6	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	0.00
	Gross Labou	r Cost (S\$)	2,440.00	1,800.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >